

## تقرير الفحص – 2007 كاتربيلر II-938G

الرقم التسلسلي: CAT09388GARTB03612 | ساعات: ٤٩٩٦٥ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٠٦

### Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Lubrication System
N/A	Auxiliary Hydraulic Valve
N/A	Equipment Parts Manual
Yes	Air Conditioning System
N/A	(Hydrostatic Drive System (Hydrostat
N/A	Supplemental Steering System
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Quick Attachment Coupler
N/A	Load Weighing System
Yes	Horn Function

### Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Controls, Levers
Ok, left mirror is missing, and the front glass and left door glass cracked	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
Not functional	Washer, Wipers
Not cooling	Air Conditioning & Heating System
N/A	Cab Floor Covering
Ok	Cab Structure, Gard
Ok	Electrical System

### Engine & Performance



Electronic	Fuel Injection Type
3126B	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
PI	Belts & Air/Oil Filters
Normal	Smoke
Ok, normal water	Coolant
Ok	Fluid Leaks
Need service	Battery Alternator

## Exterior Condition & Visual Inspection

Ok	Main Frame and Lift Arm
Ok, auto-lift not functional	Engine Hood
Ok	Access Steps and Handrails
Ok	Exterior Paint Condition
Ok	Counterweight Condition
Ok, no rear fenders	Wheel Fenders
Ok, 2 lights not functional	Lights Check
Need change	Battery Check

## Power Train Inspection

Ok	Axles and Differentials
Ok	Transmission Gearbox
Ok	Power Train force
Ok	Transmission Noise Check
Ok	Universal Joint Condition
Semi- Auto	Transfer Gear Type

## Hydraulic System

Ok	Hydraulic Leaks
Ok, right lift jack minor oil leaks	Lift and Tilt Hydraulic Jack
Ok	Steering Hydraulic Jacks



Ok

Hydraulic Pumps and Valves

## Limited Functional Testing & Operation

Functional	Steering Function Test
Functional , 4R not functional	Transmission Operation Test
Functional	Loader Stall Test
Functional	Brake System Test
Ok	Articulation Movement Check
Functional	Loader Attachment Pins
Functional, need minor service	Electrical System Check
N/A	Supplemental Steering Test

## Attachments

W2600, H1200, D900 mm	Bucket Width and Capacity
Ok, extra plate welded	Bucket Bottom Condition
Ok, no teeth	Bucket Edge & Teeth Condition
Ok	Bucket Side Condition
Ok	Attachment Coupler
Ok, welded	Bucket Rear Condition

## Tires Inspection

-	Front Right
TRIANGLE 20.5R25	Tire Brand & Size Details
60%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Front Left
HANMIX 20.5R25	Tire Brand & Size Details
100%	Tire Remaining Life Percentage
New	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Right
TRIANGLE 20.5R25	Tire Brand & Size Details
50%	Tire Remaining Life Percentage



# المعدات والاليات | تقويم المزادات

Ok, minor cut	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Left
TRIANGLE 20.5R25	Tire Brand & Size Details
60%	Tire Remaining Life Percentage
Ok, minor cut	Tire Condition Notes
Ok	Wheel Rims & Nuts

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

