

## تقرير الفحص – 2012 اطلس كوبكو F9 LF20

الرقم التسلسلي: 12A15428992008383 | ساعات: ١٥١٢٣ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٥٢

### Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Automatic Lubrication System
N/A	Diesel Particulate Filter
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade
N/A	Horn
N/A	Rear Camera
N/A	E-Cataloge
N/A	Radio
Yes	CE Mark
Need replace	Emergency Stop

### Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, only left mirror	Windows and Mirrors
Ok, gauges need service	Dashboard Screen, Gauges
Ok	Warning alarms message
Not functional	Washer, Wipers
Not cooling	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Guard
Need service	Electrical System

### Engine & Performance

Electronic	Fuel Injection System
------------	-----------------------



C9	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Normal water	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Minor	Smoke Check
Normal	Blowby
Ok	Leaks & Seals

## Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok, front right lock need service	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok	Vices
Not functional	Lights
Need change	Battery Check
Ok	Cabin Compartments
Ok	Exterior Paint Condition
N/A	Stake Down System
N/A	Kelly Drive Gear Box
Not functional	Thrust Chain / Sprockets
N/A	Drill Rod Loading System
Avilable	Drill Rod Racks
Not functional du to air copressur	Dust Collection System
Rusty	Mast Condition

## Hydraulic System

Multi leaks	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Ok	Hydraulic Pump & Valve Block



N/A	Stabilizer Cylinders
Ok, minor oil leak	Mast Angle Cylinders
Ok, minor oil leak	Drifter Cylinder

## Performance analysis

Ok	Boom Pins Condition
Ok	Hydraulic Pump Noise Check
Ok	Drive force Test
N/A	Stake Down System
Functional	Vices
N/A	Drill Rod Loading System
Not functional	Air Compressor
Not functional	Dust Collection System

## Undercarriage

60%	Bushings
70%	Track Shoes
70%	Idlers
330	:Shoe Width In Mm
50	:Track Pitch In Mm
70%	Carrier Rollers
70%	Track Rollers
70%	Track Links
60%	Sprocket Segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

