

تقرير الفحص – 2014 هيونداي Robex 330LC-9SH

الرقم التسلسلي: HHKHZ903PD0000023 | ساعات: ٢٤٩٢٠ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١٠١٧

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
Yes, not tested	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
Ok	Horn

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
Not functional	Washer, Wipers
Ok, external	Air Conditioning & Heating System
Minor cut	Cab Floor Covering
Ok	Cab Structure, Gard
Need service	Electrical System

Engine & Performance

Mechanical	Fuel Injection System
Mitubishi	Engine Model



Ok	Engine Cooling System
Ok	Engine Oil Check
Ok	Cooling System
Ok	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Minor gasket leaks	Leaks & Seals

Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok, counterweight minor welding	Bumpers & Catwalk Condition
Ok	Arm Condition
Ok	Lights
Ok	Battery Check
Ok	Cabin Compartments
Ok	Exterior Paint Condition

Hydraulic System

Minor	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Ok	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

Performance analysis

Minor loose	Boom Pins Condition
Functional	Excavator self- Drift Test



Ok	Arm Pins Condition
Ok	Hydraulic Pump Noise Check
Ok,minor loose	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok	Swing Drive and Brake Test
Ok	Drive force Test

Attachments

Bucket	Attachments model
W 5100, H 4900, D 900 mm	Size
Ok	Status
Ok	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

Undercarriage

60%	bushings
60%	Track shoes
70%	idlers
600	:shoe width in mm
80	:track pitch in mm
70%	carrier rollers
50%	Track rollers
70%	Track links
70%	Sprocket segments

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

