

تقرير الفحص – 2015 هيونداي R220LC-7

الرقم التسلسلي: HHIHN606PB000D518 | ساعات: ٨٩٧٣ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٧٣٧

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
Yes	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
N/A	Horn

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, mirrors are missing	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
N/A	Washer, Wipers
Not functional	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
Ok	Electrical System

Engine & Performance

Mechanical	Fuel Injection System
Cummins 6BTA-5.9C	Engine Model



Ok	Engine Cooling System
Ok	Engine Oil Check
Ok	Cooling System
Ok	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Minor	Smoke Check
Normal	Blowby
Ok	Leaks & Seals

Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
N/A	Lights
Ok	Battery Check
Ok	Cabin Compartments
Ok	Exterior Paint Condition

Hydraulic System

Ok	Hydraulic Leaks
Ok, 1- jack welded	Boom Hydraulic Jack
Functional	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

Performance analysis

Ok	Boom Pins Condition
Functional	Excavator self- Drift Test



Ok	Arm Pins Condition
Minor	Hydraulic Pump Noise Check
Ok	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Functional	Swing Drive and Brake Test
Ok	Drive force Test

Attachments

Bucket	Attachments model
W1150, H1200, D800 mm	Size
Minor damaged	Status
Ok	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

Undercarriage

40%	Bushings
35%	Track shoes
40%	Idlers
600	:Shoe width in mm
70	:Track pitch in mm
20%	Carrier rollers
20%	Track rollers
40%	Track links
40%	Sprocket segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

