

تقرير الفحص – 2017 هيونداي ROBEX 500LC-7

الرقم التسلسلي: HHKHNB02AE0000901 | ساعات: ٩٦٠٢ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٧٢

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
N/A	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
-	Horn

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, mirrors missing	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
Wiper missing	Washer, Wipers
Ok	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
Ok	Electrical System

Engine & Performance

Electrical	Fuel Injection System
cummins QSM11	Engine Model



Ok	Engine Cooling System
Ok	Engine Oil Check
Ok	Cooling System
Ok	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Ok	Leaks & Seals

Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok, Counterweight minor crack	Bumpers & Catwalk Condition
Ok	Arm Condition
Ok, need 3 bulbs	Lights
Ok	Battery Check
Ok	Cabin Compartments
Ok	Exterior Paint Condition

Hydraulic System

Ok	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Ok	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

Performance analysis

Ok	Boom Pins Condition
Ok	Excavator self- Drift Test



Ok	Arm Pins Condition
Ok	Hydraulic Pump Noise Check
Ok	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok	Swing Drive and Brake Test
Ok	Drive force Test

Attachments

Bucket	Attachments model
W580, H1450, D1150 mm	Size
Ok	Status
Minor crack	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

Undercarriage

70%	bushings
70%	Track shoes
L60%, R70%	idlers
600	:shoe width in mm
80	:track pitch in mm
70%	carrier rollers
60%	Track rollers
60%	Track links
80% left side minor leak	Sprocket segments

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

