

## تقرير الفحص - 2021 كاتربيلر 320

ساعات: ٢٨٣٩٠ . | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٦٩١٣٩٦

Key Features & Condition	
N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
Yes	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
N/A	Horn
Yes	Rear Camera
Yes	Machine Angle Sensors
Operator Cabin Details	
Ok	Seat and Arm Support
Ok, need lock repair	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, front window is cracked, right window need silicon seal, right mirror is missing	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Error 4576-11, Error 4576-4	Warning alarms message
Ok	Washer, Wipers
Ok	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok, no guard	Cab Structure, Guard
Ok, need minor service(check errors )	Electrical System
Engine & Performance	



# المعدات و الآليات | تقويم المزادات

Electronic

Fuel Injection System

C7.1

Engine Model

Ok

Engine Cooling System

Ok

Engine Oil Check

Ok, normal water

Coolant

Ok

Exhaust System & Muffler

Ok

Belts & Air/Oil Filters

Normal

Smoke Check

Normal

Blowby

Ok

Leaks & Seals

## Exterior Condition & Visual Inspection

Ok

Main Frame & Track Frame

Ok

Protective Covers & Sheets

Ok

Engine Hood

Ok, 2 doors lock need repair

Ok

Side Access Doors

Ok

Steps and Handrails

Ok

Boom Condition

Ok

Bumpers & Catwalk Condition

Ok

Arm Condition

Ok

Lights

Ok

Battery Check

Ok

Cabin Compartments

Ok

Exterior Paint Condition

## Hydraulic System

Ok

Hydraulic Leaks

Ok

Boom Hydraulic Jack

Ok

Hydraulic Pump & Valve Block

Ok

Bucket Hydraulic Jack

Ok

Arm Hydraulic Jack

## Performance analysis

Ok

Boom Pins Condition



شركة باندي لمزادات ش.ذ.م.م  
دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة  
هاتف: +97148861125  
[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

# المعدات و الآليات | تقويم المزادات

Ok	Excavator self- Drift Test
Ok	Arm Pins Condition
Ok	Hydraulic Pump Noise Check
Ok, minor loose	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok	Swing Drive and Brake Test
Ok	Drive force Test

Attachments	
Bucket (1.19 m <sup>3</sup> )	Attachments model
W1070,H1190,D880 mm	Size
Ok	Status
Ok	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

Undercarriage	
70%	bushings
70%	Track shoes
70%	idlers
600	:shoe width in mm
75	:track pitch in mm
70%	carrier rollers
70%	Track rollers
70%, 1 link need repair	Track links
70%	Sprocket segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأ IMPLIED أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصرياً.

