

Inspection report – 2007 Bobcat S130

Serial No: A8KA11036 | Hours: 5311 | Location: Dubai, United Arab Emirates | SKU: 981

Key Features & Condition

Safety Certification Label	N/A
Operator's Manual	N/A
Equipment Parts Manual	N/A
Air Conditioning System	N/A
Emission Compliance Label	N/A
Closed Cabin	N/A
Horn Function	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	N/A, only rear window
Gauges	Ok
Warning alarms message	ACS warning, Air flow
Washer, Wipers	N/A
Air Conditioning & Heating System	N/A
Cab Floor Covering	N/A
Cab Structure, Guard	Ok
Electrical System	Need service
Start key	Broken
Main Safty Switch	Not functional (bypass)

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	Kubota V2203-M-DI
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Minor

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok
Leaks& seals	Minor leak from fuel pump
Fuel System	Need minor service
Note :	Fuel pump solenoid valve needs changing (hard start, sudden off)

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok, minor welding, minor crack
Protective Covers & Sheets	Ok
Engine Door	Ok
Lights	Not functional
Battery Check	Ok
Exterior Paint Condition	Ok, fully repainted

Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital (drive motor)	Ok
Hydraulic Pumps and Valves	Ok

Limited Functional Testing & Operation

Drive Function Test	Functional
Skid steer Stall Test	Functional
Brake System Test	Functional
Attachment Pins	Functional
Final Drive Motors Test	Functional
Park Break	Not functional

Attachments

Attachments model	Bucket
Size	W1530, H310, D500 mm

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Bottom condition	Ok
Edge & teeth condition	Ok, no teeth
Bucket side condition	Ok
Coupler status	Ok

Tires Estimated Remaining Life %

Front Right	100%
Front Left	100%
Rear Right	100%
Rear Left	100%
Size	10-16.5
Type	Tube less
wheel Rims & Nuts	Ok, 2 nuts missing

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

