

Inspection report – 2019 Bobcat S570

Serial No: ALM428711 | Hours: 8288 | Location: Dubai, United Arab Emirates | SKU: 755

Key Features & Condition

Safety Certification Label	N/A
Operator's Manual	N/A
Equipment Parts Manual	N/A
Air Conditioning System	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Horn Function	N/A

Operator Cabin Details

Seat and Arm Support	Ok, need upholstery
Cab Doors & covers	N/A
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok
Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	N/A
Air Conditioning & Heating System	N/A
Cab Floor Covering	N/A
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	Doosan KDICL02,4LEA
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



Smoke	Normal
Coolant	Ok, normal water
Leaks& seals	Ok

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok, welding at the right lift arm base
Protective Covers & Sheets	Ok
Engine Door	Ok
Lights	2 broken lights, needs 5 bulbs
Battery Check	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok, minor
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital	Ok
Hydraulic Pumps and Valves	Ok

Limited Functional Testing & Operation

Steering Function Test	Ok
Skid steer Stall Test	Ok
Brake System Test	Ok
Attachment Pins	Ok
Final Drive Motors Test	Ok
Electrical System Check	Ok

Attachments

Attachments model	Bucket
Size	W1800, H700 mm
Bottom condition	Ok, minor bend
Edge & teeth condition	minor damage, no teeth
Bucket side condition	Ok
Coupler status	Ok

Tires Estimated Remaining Life %

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



Front Right	50%
Front Left	40%
Rear Right	80%
Rear Left	80%
Size	10.16.5
Type	Tubless
Wheel Rims & Nuts	2 wheel rims has minor dents, 3 nuts are missing

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

