

Rapport d'inspection – 2014 Bobcat S450

Numéro de série: AUVB11125 | Heure: 2027 | Lieu: Dubai, Émirats arabes unis | SKU: 760

Key Features & Condition

Safety Certification Label	N/A
Operator's Manual	N/A
Equipment Parts Manual	N/A
Air Conditioning System	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Horn Function	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	N/A
Control Levers, Control Stick	Ok
Windows and Mirrors	N/A
Gauges	Ok
Warning alarms message	Error (E000731-21)
Washer, Wipers	N/A
Air Conditioning & Heating System	N/A
Cab Floor Covering	N/A
Cab Structure, Guard	Ok
Electrical System	Ok, Check Error

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	Doosan ED1CL01.8LEA
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Smoke	Normal
Coolant	Ok
Leaks& seals	Ok

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Protective Covers & Sheets	Ok
Engine Door	Ok
Lights	Ok, front1- craked light, rear lights not functional
Battery Check	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital	Ok
Hydraulic Pumps and Valves	Ok

Limited Functional Testing & Operation

Steering Function Test	Ok
Skid steer Stall Test	Ok
Brake System Test	Ok
Attachment Pins	Ok
Final Drive Motors Test	Ok

Attachments

Attachments model	Bucket
Size	W2100, H800, D550 mm
Bottom condition	Ok
Edge & teeth condition	Ok, no teeth
Bucket side condition	Ok
Coupler status	Ok

Tires Estimated Remaining Life %

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Front Right	30% BOBCAT
Front Left	30% XTERA-WALL
Rear Right	60% (Recapped tire) GALAXY
Rear Left	60% (Recapped tire) GUARD DOG HD
Size	10.16.5
Type	Tubless
wheel Rims & Nuts	Ok

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

