

Rapport d'inspection – 2017 Caterpillar 980L

Numéro de série: CAT0980LCD8Z10264 | Heure: 20567 | Lieu: United Arab Emirates | SKU: 773

Key Features & Condition

| | |
|--------------------------------------|-----|
| Safety Certification Label | N/A |
| Automatic Lubrication System | N/A |
| Auxiliary Hydraulic Valve | N/A |
| Equipment Parts Manual | N/A |
| Air Conditioning System | Yes |
| Hydrostatic Drive System (Hydrostat) | N/A |
| Supplemental Steering System | Yes |
| Operator's Manual | N/A |
| Emission Compliance Label | N/A |
| Quick Attachment Coupler | N/A |
| Load Weighing System | N/A |
| Horn Function | Yes |

Operator Cabin Details

| | |
|-----------------------------------|---|
| Seat and Arm Support | Ok |
| Cab Doors & covers | Ok |
| Controls, Levers | Ok |
| Windows and Mirrors | Ok |
| Dashboard Screen, Gauges | Ok |
| Warning alarms message | Implement calibration; fuel water separator is full |
| Washer, Wipers | Ok, rear wiper is not functional |
| Air Conditioning & Heating System | Ok |
| Cab Floor Covering | Ok |
| Cab Structure, Guard | Ok,no Guard |
| Electrical System | Ok |

Engine & Performance

| | |
|---------------------|------------|
| Fuel Injection Type | Electronic |
|---------------------|------------|

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|--------------------------|--------|
| Engine Model | C13 |
| Engine Cooling System | Ok |
| Engine Oil Check | Ok |
| Blowby | Normal |
| Exhaust System & Muffler | Ok |
| Belts & Air/Oil Filters | Ok |
| Smoke | Normal |
| Coolant | Ok |
| Fluid Leaks | Ok |

Exterior Condition & Visual Inspection

| | |
|----------------------------|----------------------------------|
| Main Frame and Lift Arm | Ok |
| Engine Hood | Ok |
| Access Steps and Handrails | Ok, first step is missing |
| Exterior Paint Condition | Ok |
| Counterweight Condition | Ok |
| Wheel Fenders | Ok |
| Lights Check | Ok, need 3 bulbs |
| Battery Check | Ok |
| Side Doors & Covers | 2-missing covers, 1-missing door |

Power Train Inspection

| | |
|---------------------------|-----------------------------------|
| Axles and Differentials | Ok |
| Transmission Gearbox | Ok, second gear is not functional |
| Power Train force | Ok |
| Transmission Noise Check | Ok |
| Universal Joint Condition | Ok |
| Transfer Gear Type | Semi-Auto |

Hydraulic System

| | |
|------------------------------|----|
| Hydraulic Leaks | Ok |
| Lift and Tilt Hydraulic Jack | Ok |
| Steering Hydraulic Orbital | Ok |
| Steering Hydraulic Jacks | Ok |

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Hydraulic Pumps and Valves

Ok

Limited Functional Testing & Operation

Steering Function Test

Ok

Transmission Operation Test

Ok, second gear is not operational

Loader Stall Test

Ok

Brake System Test

Ok

Articulation Movement Check

Ok

Loader Attachment Pins

Ok

Supplemental Steering Test

Ok

Attachments

Bucket Width and Capacity

W3350, H1500, D1250 (5.7 m³)

Bucket Bottom Condition

Ok, armored

Bucket Edge & Teeth Condition

Ok

Bucket Side Condition

Ok

Attachment Coupler

Ok

Tires Inspection

Front Right

-

Tire Brand & Size Details

BKT (29.5R25)

Tire Remaining Life Percentage

70%

Tire Condition Notes

Ok, tiny cuts

Wheel Rims & Nuts

Ok

Front Left

-

Tire Brand & Size Details

BKT (29.5R25)

Tire Remaining Life Percentage

30%

Tire Condition Notes

Some wears, cuts

Wheel Rims & Nuts

Ok

Rear Right

-

Tire Brand & Size Details

BKT (29.5R25)

Tire Remaining Life Percentage

80%

Tire Condition Notes

Ok

Wheel Rims & Nuts

Ok, 1-nut is missing

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|--------------------------------|-------------------|
| Rear Left | - |
| Tire Brand & Size Details | BKT (29.5R25) |
| Tire Remaining Life Percentage | 40% |
| Tire Condition Notes | Minor wears, cuts |
| Wheel Rims & Nuts | Ok |

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

