

Rapport d'inspection – 2018 JCB 540-180

Numéro de série: JCB5RA7GTJ2728317 | Heure: 7474 | Lieu: United Arab Emirates | SKU: 752

Key Features & Condition

Safety Certification Label N/A Axle Based 4Wd Yes **Electric Powered** N/A **Equipment Parts Manual** N/A **Electric Operating System** Yes Horn Function Yes Travel Alarm Yes N/A Operator'S Manual

Emission Compliance Label Yes (STI4)

Diesel Powered Yes
Rear Camera Yes

Operator Cabin Details

Seat And Arm Support Ok
Control Levers, Control Swithes Ok
Dashboard Screen, Gauges Ok
Warning Alarms Message Ok
Electrical System Ok
Windows/ Mirrors/ Wipers Ok
Floor Mates Ok

Engine

Model JCB 430 Dieselmax Stage V

Injection Type Electronic

Leaks Ok
Oil Condition Ok
Exhaust Smoke Normal

Cooling System Ok

Coolant Ok, normal water

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



PLANT & EQUIPMENT AUCTIONS

Sound Ok

Blow By Normal

Belts Ok Power Ok

Exterior Condition & Visual Inspection

Chassis Ok Sheet Metal Ok Side Doors Ok **Boom Condition** Ok Boom Linkage / Guides Ok Paintwork Ok Cooler Grill Ok Frame Condition Ok Outriggers Ok **Batteries** Ok

Hydraulic System

Hoses,Lines,Swivel Ok
Pump And Valve Bloc Ok
Steering Cylinder Ok
Boom Lift Cylinder(S) Ok

Telescopic Boom Cylinders Functional

Carriage Tilt Cylinder Ok
Frame Leveling Cylinders N/A
Stabilizer Cylinders Ok

Leaks Telescopic boom cylinder fitting oil leak

(requires welding)

Drivetrain

Transmission Ok
Transfar Gear Type Auto
Transfer Case / Drop Box Ok
Front / Rear Axle Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com





Limited Functional Testing & Operation

Drive Forward Ok
Drive Reverse Ok

Steering Ok (3 types)

Platform Function Controls

Boom Extension

Ok

Fork Angle Movment

Ok

Wheel Bearing

Ok

Platform Control

Ok

Brake System

Ok

Chiffing

Ok

Ok

Ok

Ok

Tires Condition / Type / Size

 Axle 1 Right
 50% - ALLIANCE 15.5/80 -24 Tubeless

 Axle 1 Left
 50% - ALLIANCE 15.5/80 -24 Tubeless

 Axle 2 Right
 100% -HAULKING 15.5/80 -24 Tubeless

 Axle 2 Left
 10% - GALAXY 15.5/80 -24 Tubeless

Notes

The Telescopic Telehandler is in good working condition, with all major components intact and functioning as intended. However, there is an oil leak detected at the telescopic boom cylinder fitting.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

