

تقرير الفحص – 2018 جيه سي بي 380LC

الرقم التسلسلي: PUNJD38CCJ2500802 | ساعات: ١٧١٧٠ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٥٣

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
Yes	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
N/A	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
N/A	Horn
N/A	Rear Camera
N/A	E-Cataloge
N/A	Radio

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, front down glass has crack	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
Ok, not functional	Washer, Wipers
Extenal, ok	Air Conditioning & Heating System
N/A	Cab Floor Covering
Ok	Cab Structure, Guard
Need service	Electrical System



Engine & Performance

Electronic, need service
 JCB DIESELMAX 672 TCAE Electronic
 Engine.
 Ok
 Ok
 Ok,normal water
 Ok
 Ok
 Normal
 Normal
 Ok

Fuel Injection System
 Engine Model
 Engine Cooling System
 Engine Oil Check
 Coolant
 Exhaust System & Muffler
 Belts & Air/Oil Filters
 Smoke Check
 Blowby
 Leaks & Seals

Exterior Condition & Visual Inspection

Ok, minor welding on boom lift jack base
 Ok
 Ok, lift support is missing
 Ok
 Ok
 Ok
 Ok
 Ok
 Minor crack, minor welding on bucket pin side
 Ok, boom light is missing, need 2 bulbs
 Ok
 Ok, fuse cover is missing
 Ok, some parts repainted

Main Frame & Track Frame
 Protective Covers & Sheets
 Engine Hood
 Side Access Doors
 Steps and Handrails
 Boom Condition
 Bumpers & Catwalk Condition
 Arm Condition
 Lights
 Battery Check
 Cabin Compartments
 Exterior Paint Condition

Hydraulic System

Ok, minor
 Ok
 Ok
 Ok
 Ok

Hydraulic Leaks
 Boom Hydraulic Jack
 Hydraulic Pump & Valve Block
 Bucket Hydraulic Jack
 Arm Hydraulic Jack



Performance analysis

Ok, lift cylinder pin minor loose	Boom Pins Condition
Ok	Excavator self- Drift Test
Ok	Arm Pins Condition
Ok	Hydraulic Pump Noise Check
Ok, minor loose	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok, swing drive oil level is high	Swing Drive and Brake Test
Ok, right is little weaker	Drive force Test

Attachments

Bucket	Attachments model
W1550, H1300, D115 mm	Size
Ok	Status
Ok	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

Undercarriage

50%	Bushings
60%	Track Shoes
R70%, L50%	Idlers
600	:Shoe Width In Mm
80	:Track Pitch In Mm
60%	Carrier Rollers
60%	Track Rollers
60%	Track Links
70%	Sprocket Segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

