

تقرير الفحص – 2012 دووسان DX340LC

ساعات: ٩٧٨١.٠ | الموقع: دبي, الإمارات العربيّة المتّحدة | رقم التعريف: ١٣٢٠٧٠٣

	Key Features & Condition
N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
Yes	Hydraulic Hammer Lines
N/A	Grapple And Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System Addblue
N/A	Stabilizer Blade Condition
Yes	Horn
	Operator Cabin Details
Ok	Seat And Arm Support
Ok	Cab Doors & Covers
Ok	Control Levers, Control Stick
Ok, no mirrors	Windows And Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning Alarms Message
Missing	Washer, Wipers
Not functional	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
Ok	Electrical System
	Engine & Performance
Electronic	Fuel Injection System
Doosan DL08	Engine Model

Ok, need rust cleaning



Engine Cooling System

المعدات والأليات تقويم المزادات

Ok Engine Oil Check
Ok, normal water Cooling System

Ok, end muffler need minor welding Coolant

Ok Exhaust System & Muffler

Ok Belts & Air/Oil Filters
mal Smoke Check

Normal Smoke Check Normal Blowby

Ok, minor oil leak from head cover gasket

Leaks & Seals

Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps And Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
Ok	Lights
Ok	Battery Check
Ok	Cabin Compartments

Ok, some parts repainted

Ok Hydraulic Leaks
Ok Boom Hydraulic Jack
Functional, little weak Hydraulic Pump & Valve Block
Ok Bucket Hydraulic Jack

Ok Arm Hydraulic Jack

Performance analysis

Exterior Paint Condition

Hydraulic System

Ok, minor loose Boom Pins Condition

Weak Excavator Self- Drift Test

Ok Arm Pins Condition



شركة باندي لمزادات ش.ذ.م.م



Bucket Pins Condition Slewing Ring Bearing Movement Che Swing Drive And Brake Te	Ok, minor Ok, minor loose Ok Ok Ok
Attachmen	
t Attachments Mod	Bucket
n Si	W1060, H1200, D1000 mm
Stat Stat	Ok
Coupler Stat	Ok
A Second Attachments Mod	N/A
A Si	N/A
A Stat	N/A
Undercarria	
Bushin	50%
Track Sho	60%
idle	60%
) :Shoe Width In M	600
Track Pitch In M	80
Carrier Rolle	50%
Track Rolle	40%
Track Lin	60%
Sprocket Segmer	60%

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

