

PLANT & EQUIPMENT

تقرير الفحص – 2006 كوبيلكو CKE1350

الرقم التسلسلي: GN0302049 | ساعات: ٣٣٢٩٤ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١١٨٧

Key Features & Condition

N/A	CE Labeling
N/A	Tachograph
N/A	Auto Lube
Yes, external	A/C
N/A	Extended Fuel tank
N/A	Horn
Yes, not assembled	Hook speed sensor
Yes	Boom angle sensor
Yes	Radiuous sensor
Yes	Hook weight sensor
Yes	Load sensor
Yes	Hook

Truck Cab

Ok, need upholstery	Driver Seat
Ok	Switches, Levers
Ok	Gauges, Warn Lights
External, not cooling	Aircon / Heater
Ok	Cab Doors
Ok, no mirrors	Windows, Mirrors
Ok, only front	Wipers, Washers
Ok	Interior, Covers

Engine

Electronic	Injection Type
Mitsubishi 6D24-TLU2H	Engine Model
Ok, minor from injector cover	Leaks, Seals
Ok	Oil Condition
Ok	Exhaust/Muffler



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Ok	Cooling System
Ok, minor	Smoke, Fume
Normal	Blow By
Ok, ac belt missing	Belts, Pulleys
Normal water	Coolant Condition

Visual inspection exterior

Ok	Chassis, Frames
Ok	Sheet Metal, Covers
Ok	Steps, Grab Irons
Ok	Paintwork
Ok, not assembled	Boom Condition
Ok	Cooler Grill
Ok, self assemble type	Bumpers
Ok, only 2, 1 need bulb	Lights
Ok	Batteries
Avilable, not assembled	Main Hook
Avilable, not assembled	Auxiliary Hook
Ok	machine punched number

Hydraulics

Ok	Hydraulic Leaks
Ok	Hydraulic Pump / Valve
Ok	hydraulic stabilizer

Crane Condition / Limited Test

Ok	Drive Forward & Back
Ok	Controls, Levers
Avilable, not assembled	Boom Conditions
N/A	Telescopic Segments
Ok, only outriggers	Hydraulic Cylinders
Ok	Swing Bearing / Drive
Ok	Hose Lines
Not assembled	Lift Limitations



PLANT & EQUIPMENT

Not assembled

Main Hook

Not assembled

Auxiliary Hook

Ok

Outriggers

Ok

Boom Pins Condition

Ok

Hydraulic Pump Noise Check

Undercarriage

60%

Bushings Pin

60%

Track shoes

60%

Idlers

2 pic 40%, 2 pic need change

Carrier rollers

50%

Track rollers

40%, minor loose

Track links pine

70%

Sprocket segments

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com