

PLANT & EQUIPMENT

تقرير الفحص – 2007 رينو KERAX

الرقم التسلسلي: VF634DPA77D000807 | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١٢٠٠

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Shift
N/A	Semi-Automatic
N/A	Cruise Control
N/A	Cabin Refrigerator
N/A	Add blue
Yes	Hill stand aid function
Yes	Horn off-on
N/A	Tachograph
N/A	Auto Lube
Ok	A/C
N/A	Navigation
Yes	ABS
N/A	Driver bed
Yes	Moving off aid
N/A	Lane departure warning system
N/A	Extended Fuel tank
Yes	Retarder
N/A	Rear Axle Lifter
N/A	Radio
N/A	TRC
N/A	Camera sensor
Yes	Differential lock
Yes	Advanced emergency brake assist

Truck Cabin Details

Ok	Seat and Arm Support
Ok, driver door lock need service	Cab Doors & covers
Ok	Controls, Levers



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Ok	Windows and Mirrors
Ok, screen not visual sunburnt, air gauge not functional	Dashboard Screen, Gauges
Screen not visual sunburnt	Warning alarms message
Ok	Washer, Wipers
Not cooling	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Interior, Covers
Ok	Passenger Seat
N/A	Radio

Engine & Performance

Electronic	Fuel Injection Type
Renault DXI 11	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Ok	Coolant
Ok	Fluid Leaks

Exterior Condition & Visual Inspection

Ok	Chassis, Frames
Ok	Sheet Metal, Covers
Ok	Steps, Grab Irons
Ok	Paintwork
Ok	Cooler Grill
Ok	Bumpers
Ok	Lights / Batteries
Ok	Fenders
Ok	Drum
Ok	Drum Pedestals



PLANT & EQUIPMENT

Ok	Drum Rollers
Ok	Drum Roller Ring
Ok	Flights
Ok	Chute Rotator
Ok	Water Tank
Ok	Exterior Mixer Controls

Power Train

Ok, minor leak at the right second differential	Axels/Differentials
Ok	Stabilizers, Beams
Ok	Rubber Sleeves
Ok	Brake Pads/Disks
Ok	Compressor
Ok	Transfer Gear
Ok	Universal Joints
Ok, manual	Transmission
Functional, need minor service	Clutch
N/A	Non-Driven Rear Drop Axle

hydraulics

Functional	PTO Pump
N/A	hydraulic cylinder
Ok	cabine lift cylinder & valve
Ok	Mixer cylinder
Ok	Mixer Drive Motor

Truck Limited Functional Test

Ok	Transmission Forward
Ok	Transmission Reverse
N/A	Automatic Group Select
Ok	Service Brake
Ok	Park Brake
Need minor service	Electrics
Ok	Retarder



PLANT & EQUIPMENT

Tires

R 90%, L 90%	(%) Axle 1 / RHS mm (%) / LHS mm
R 90%, L 90%	(%) Axle 2 Inside / RHS mm (%) / LHS mm
R 90%, L 90%	(%) Axle 2 Outside / RHS mm (%) / LHS mm
R 90%, L 90%	(%) Axle 3 Inside / RHS mm (%) / LHS mm
R 90%, L 90%	(%) Axle 3 Outside / RHS mm (%) / LHS mm
11.00 R20	Tire Size

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

