

## تقرير الفحص – 2008 هيونداي HL770-7A

الرقم التسلسلي: LB0411043 | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٨٨

### Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Lubrication System
N/A	Auxiliary Hydraulic Valve
N/A	Equipment Parts Manual
Yes	Air Conditioning System
N/A	(Hydrostatic Drive System (Hydrostat
Yes	Supplemental Steering System
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Quick Attachment Coupler
N/A	Load Weighing System
Yes	Horn Function

### Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Functional, need minor service	Controls, Levers
Ok, left centr mirror is missing	Windows and Mirrors
Ok, screen not functional	Dashboard Screen, Gauges
Gear box warning	Warning alarms message
Ok	Washer, Wipers
Ok	Air Conditioning & Heating System
N/A	Cab Floor Covering
Ok	Cab Structure
Need minor service	Electrical System

### Engine & Performance

Electronic	Fuel Injection Type
Cummins SQL	Engine Model



Ok	Engine Cooling System
Ok, need change	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Minor	Smoke
Ok, normal water	Coolant
Ok	Fluid Leaks

## Exterior Condition & Visual Inspection

Ok	Main Frame and Lift Arm
Ok	Engine Hood
Ok	Access Steps and Handrails
Ok, Fully repainted	Exterior Paint Condition
Ok	Counterweight Condition
Ok, no rear fenders	Wheel Fenders
Not functional	Lights Check
Need change	Battery Check

## Power Train Inspection

Ok	Axles and Differentials
Ok	Transmission Gearbox
Ok	Power Train force
Ok	Transmission Noise Check
Ok	Universal Joint Condition
Semi-auto	Transfer Gear Type

## Hydraulic System

Minor oil leaks from Fittings	Hydraulic Leaks
Ok	Lift and Tilt Hydraulic Jack
Ok	Steering Hydraulic Orbital
Ok, minor oil leaks	Steering Hydraulic Jacks
Functional	Hydraulic Pumps and Valves



### Limited Functional Testing & Operation

Functional	Steering Function Test
Functional	Transmission Operation Test
Functional	Loader Stall Test
Functional	Brake System Test
Functional	Articulation Movement Check
Ok, tilt pin minor loose	Loader Attachment Pins
N/A	Supplemental Steering Test

### Attachments

W3000, H1500, D1100 mm	Bucket Width and Capacity
Ok, minor welding	Bucket Bottom Condition
Ok	Bucket Edge & Teeth Condition
Ok	Bucket Side Condition
Ok	Attachment Coupler

### Tires Inspection

-	Front Right
MARF 26.5-25	Tire Brand & Size Details
100%	Tire Remaining Life Percentage
New	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Front Left
VIZZONI 26.5-25	Tire Brand & Size Details
100%	Tire Remaining Life Percentage
New	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Right
BKT 26.5-25	Tire Brand & Size Details
80%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Left



# المعدات والليات | تقويم المزادات

BKT 26.5-25

80%

Ok

Ok

Tire Brand & Size Details

Tire Remaining Life Percentage

Tire Condition Notes

Wheel Rims & Nuts

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

