

PLANT & EQUIPMENT

تقرير الفحص – 2010 دووسان D50C-5

الرقم التسلسلي: N3-01012 | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١١٥١

Key Features & Condition

N/A	Safety Certification Label
N/A	Fork Extension
N/A	Draw Bar
Yes	Back-up Alarm
Yes	Head Lights
Yes	Seat Belt
N/A	Air Condition
N/A	Propane Tank
N/A	Horn

Operator Cabin Details

Need upholstery	Seat and Arm Support
N/A	Cab Doors & covers
Need service	Control Levers, Control Stick
N/A	Windows and Mirrors
Not functional	Dashboard Screen, Gauges
Not functional	Warning alarms message
N/A	Washer, Wipers
N/A	Air Conditioning & Heating System
N/A	Cab Floor Covering
N/A	Cab Structure, Gard
Need service	Electrical System

Engine & Performance

Mechanical	Fuel Injection System
Doosan DB-58	Engine Model
Ok	Engine Cooling System
Ok, need change	Engine Oil Check
Ok	Coolant



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Ok, minor leak from head, oil sump	Leaks & Seals

Exterior Condition & Visual Inspection

Ok	Chassis
Ok	Sheet Metal
N/A	Door Handles
Ok	Cooler Grill
Ok	Counterweight
Need 2 bulbs	Lights
Need change	Batteries
Ok	Exterior Paint Condition

Transmission

Ok	Axels
Ok, Need minor service , (shifting)	Gearbox
Ok	Universal Joints
Minor leak, wheel hub leaks	Differentials
Ok	Brake Drums/Disk
Ok	Clutch

Hydraulic System

Ok	Hoses & Lines
Ok	Pump And Valve Bloc
Ok	Lift & Tilt Cylinders
N/A	Fork side shift Cylinder
Ok	Steering Cylinder
N/A	Fork Open-Close Cylinder

Limited Functional Test

Ok	Drive Forward
----	---------------



PLANT & EQUIPMENT

Ok	Drive Reverse
Ok	Service Brake
Ok	Steering
Ok	Wheel Bearing
Ok	Park Brake
Ok	Lift, Tilt, Control
N/A	Fork side shift

Tools

H 2165 mm, Ok	Mast, size & condition
L 2100, w 200 mm	Fork 1, Size & Type, Condition
N/A	Fork 2, Size & Type, Condition
-	% Tires Condition
R70%, L50%, size 7.5 R16	<html>Axle 1 Inside mm (%) </html>
R60%, L50%, size 7.5 R16	<html>Axle 1 Outside mm (%)</html>
70%, size 7.00 - 12	<html>Axle 2 RHS mm (%) </html>
60%, size 7.00 - 12	<html>Axle 2 LHS mm </html>

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

