

تقرير الفحص – 2012 كاتربيلر 950H

الرقم التسلسلي: CAT0950HKJ5J01763 | ساعات: ٣٢٠٠٥ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١٠٢٠

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Lubrication System
N/A	Auxiliary Hydraulic Valve
N/A	Equipment Parts Manual
Yes	Air Conditioning System
N/A	(Hydrostatic Drive System (Hydrostat
Yes	Supplemental Steering System
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Quick Attachment Coupler
N/A	Load Weighing System
N/A	Horn Function

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Controls, Levers
Ok	Windows and Mirrors
Ok, fuel gauge need service	Dashboard Screen, Gauges
Ok	Warning alarms message
Ok	Washer, Wipers
Ok	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure
Ok	Electrical System

Engine & Performance

Electronic	Fuel Injection Type
------------	---------------------



C7	Engine Model
Ok	Engine Cooling System
Ok, gauge not original	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok, filters need change	Belts & Air/Oil Filters
Minor	Smoke
Normal water	Coolant
Minor Gasket leaks	Fluid Leaks
Little weak	Power

Exterior Condition & Visual Inspection

Ok	Main Frame and Lift Arm
Ok	Engine Hood
Ok	Access Steps and Handrails
Ok	Exterior Paint Condition
Ok	Counterweight Condition
Ok	Wheel Fenders
Ok	Lights Check
Need change	Battery Check
Ok	Covers

Power Train Inspection

Ok	Axles and Differentials
Functional	Transmission Gearbox
Little weak	Power Train force
Ok	Transmission Noise Check
Ok	Universal Joint Condition
Semi- auto	Transfer Gear Type

Hydraulic System

Ok, minor leaks	Hydraulic Leaks
Ok, tilt minor leak	Lift and Tilt Hydraulic Jack
Ok, left minor leak	Steering Hydraulic Jacks



Ok

Hydraulic Pumps and Valves

Limited Functional Testing & Operation

Functional	Steering Function Test
Functional	Transmission Operation Test
Ok	Loader Stall Test
Ok, park break need service	Brake System Test
Ok, minor loose	Articulation Movement Check
Ok, minor loose	Loader Attachment Pins

Attachments

W2800, H1300, D950 mm	Bucket Width and Capacity
Minor welding	Bucket Bottom Condition
Ok, no teeth	Bucket Edge & Teeth Condition
Ok	Bucket Side Condition
N/A	Attachment Coupler

Tires Inspection

-	Front Right
Advance 23.5R25	Tire Brand & Size Details
70%	Tire Remaining Life Percentage
Good,Tubeless	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Front Left
Advance 23.5R25	Tire Brand & Size Details
80%	Tire Remaining Life Percentage
Good,Tubeless	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Right
Advance 23.5R25	Tire Brand & Size Details
80%	Tire Remaining Life Percentage
Good,Tubeless	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Left



Advance 23.5R25

80%

Good, Tubeless

Ok

Tire Brand & Size Details

Tire Remaining Life Percentage

Tire Condition Notes

Wheel Rims & Nuts

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

