

تقرير الفحص – 2013 كاتربيلر TH414

الرقم التسلسلي: YC5000000TBZ00776 | ساعات: ١٢٥٢٠ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١٠١٦

Key Features & Condition

Yes	Safety Certification Label
N/A	Axle Based 4WD
N/A	Electric Powered
N/A	Equipment Parts Manual
N/A	Electric Operating System
Yes	Horn Function
Yes	Travel Alarm
N/A	Operator's Manual
N/A	Emission Compliance Label
Yes	Diesel Powered
Yes (3 types)	Distinct Steering Modes

Operator Cabin Details

Need upholstery	Seat and Arm Support
Ok	Control levers, Control swithes
Screen not functional	Dashboard Screen, Gauges
Maintinance alarm	Warning alarms message
Need service	Electrical System
wipers not functional , right mirror cracked	Windows/ mirrors/ Wipers
Ok	Floor Mats
Ok	Air Conditioning & Heating System

Engine

C4.4	Model
Electronic	Injection Type
Ok	Leaks
Ok	Oil Condition
Normal	Exhaust Smoke



Ok	Cooling System
normal water	Coolant
Ok	Sound
Normal	Blow By
Ok	Belts
Ok	Power

Exterior Condition & Visual Inspection

Ok	Chassis
Ok	Sheet Metal
Ok	Side Doors
Ok	Boom Condition
Ok	Boom Linkage / Guides
Ok	Paintwork
Ok	Cooler Grill
Ok	Frame Condition
Ok	Outriggers
Ok	Batteries
Ok	Lights
Ok	Fenders

Hydraulic System

OK	Hoses, Lines, Swivel
Functional	Pump And Valve Bloc
Functional	Steering Cylinder
Functional, sensor need service	(Boom Lift Cylinder(s
Functional	Telescopic Boom Cylinders
Functional	Carriage Tilt Cylinder
Functional	Frame Leveling Cylinders
Functional	Stabilizer Cylinders
Ok	Leaks

Drivetrain

Ok	Transmission
----	--------------



semi auto

Ok

Ok

Transfar Gear type

Transfer Case / Drop Box

Front / Rear Axle

Limited Functional Testing & Operation

Functional

Drive Forward

Functional

Drive Reverse

Functional

Steering

Functional

Platform Function Controls

Functional

Boom Extension

Functional

Fork angle movment

Functional

Wheel Bearing

Functional

brake system

Functional, need minor elecrical service

Lifting

Tires condition / Type / Size

70% Armour 15.5/80-24 tubless

Axle 1 Right

70% Armour 15.5/80-24 tubless

Axle 1 Left

70% Armour 15.5/80-24 tubless

Axle 2 Right

70% Armour 15.5/80-24 tubless

Axle 2 Left

Attachments

Ok

Coupler Condition

Fork

Tool1

L1150,W100 mm

Size

Ok

Condition

N/A

Tool 2

N/A

Size

N/A

Condition

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

