

تقرير الفحص – 2013 فولفو L105

الرقم التسلسلي: VCE0L105C00001073 | ساعات: ١٥٢٧٥ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٧٧

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Lubrication System
N/A	Auxiliary Hydraulic Valve
N/A	Equipment Parts Manual
N/A	Air Conditioning System
N/A	(Hydrostatic Drive System (Hydrostat
N/A	Supplemental Steering System
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Quick Attachment Coupler
N/A	Load Weighing System
N/A	Horn Function

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Controls, Levers
Ok, left mirror broken	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Park break failure/ reduced shift function	Warning alarms message
Ok	Washer, Wipers
Not cooling	Air Conditioning & Heating System
Ok, not original	Cab Floor Covering
Ok	Cab Structure, Gard
Ok	Electrical System

Engine & Performance

Electronic	Fuel Injection Type
------------	---------------------



Volvo D7D	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Ok	Coolant
Ok	Fluid Leaks

Exterior Condition & Visual Inspection

Ok	Main Frame and Lift Arm
Ok	Engine Hood
Ok	Access Steps and Handrails
Ok, repainted	Exterior Paint Condition
Ok	Counterweight Condition
Ok	Wheel Fenders
2- Ok, 4 not functional	Lights Check
Ok	Battery Check

Power Train Inspection

Ok	Axles and Differentials
Ok	Transmission Gearbox
weak du to park break	Power Train force
Ok	Transmission Noise Check
Ok	Universal Joint Condition
Semi- auto	Transfer Gear Type

Hydraulic System

Ok	Hydraulic Leaks
Ok	Lift and Tilt Hydraulic Jack
Ok	Steering Hydraulic Orbital
Ok	Steering Hydraulic Jacks
Ok	Hydraulic Pumps and Valves



Limited Functional Testing & Operation

Ok	Steering Function Test
Ok	Transmission Operation Test
Ok	Loader Stall Test
Ok	Brake System Test
Ok	Articulation Movement Check
Ok	Loader Attachment Pins

Attachments

W1350, h1250, d950 mm	Bucket Width and Capacity
Ok	Bucket Bottom Condition
Ok	Bucket Edge & Teeth Condition
Ok	Bucket Side Condition
Ok	Attachment Coupler

Tires Inspection

-	Front Right
China 23.5-25	Tire Brand & Size Details
100%	Tire Remaining Life Percentage
New, tube type	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Front Left
China 23.5-25	Tire Brand & Size Details
100%	Tire Remaining Life Percentage
New, tube type	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Right
Green 23.5-25	Tire Brand & Size Details
100%	Tire Remaining Life Percentage
New, tube type	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Left
Gann shan 23.5-25	Tire Brand & Size Details



المعدات والآليات | تقويم المزادات

100%
New, tube type
Ok

Tire Remaining Life Percentage
Tire Condition Notes
Wheel Rims & Nuts

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

