

PLANT & EQUIPMENT

تقرير الفحص – 2014 كوماتسو GD705-5

الرقم التسلسلي: KMTGD031JEA026087 | الموقع: Dubai, الإمارات العربية المتحدة | رقم التعريف: ١١٥٦

Key Features & Condition

N/A	Safety Certification Label
N/A	Supplemental Steering System
N/A	(Ground Loosening Tool (Scarifier
N/A	Emission Compliance Label
N/A	Snowplow Attachment
N/A	Equipment Parts Manual
Yes	Ripper Control Valve
Yes	All-Wheel Drive System
Yes	(Ground Tearing Tool (Ripper
N/A	Operator's Manual
N/A	Front Plow Blade

Operator Cabin Details

Ok	Seat
Ok	control levers
Ok, dashboard cover broken,	Dashboard Gauges & Lights
E01,CA428 Engine	Warning alarms Lights, Message
Not cooling	Air conditioning
Ok	Cab Floor Covering
Ok	Windows and Mirrors
Ok	Cab Doors
Not functional	Windshield Wipers and Washer
Ok, one step on the driver door is broken	Access Steps and Handles
Ok	Cab Structure, Guard
Need minor service	Electrical System

Engine & Performance

Mechanical	Fuel Injection Type
KOMATSU SAA6D114E-3	Engine Model Details



PLANT & EQUIPMENT

Minor gasket leak, oil sump, engine front side,
1 injector diesel leak
Ok, need change
Ok
Normal
Ok
Normal
Ok
Ok, normal water

Fluid Leaks and Seals

Engine Oil Check

Exhaust System and Muffler

Exhaust Smoke

Engine Cooling System

Engine Blow-by Check

Belts and Air/Oil Filters

Coolant Check

Exterior Condition & Visual Inspection

Ok	Main Frame Structure
Ok	Cabin Body Condition
Ok	Y-Frame Structure
Ok	Y-Frame Pivot Joint
Ok	Circle Frame & Brackets
Ok	Circle Support Brackets
Ok	Circle Gear
Ok	Blade Slide Wear Strips
Ok	Steering Linkage
Ok	Underbody Protection Plates
Ok	Exterior Paint Condition
-	Lights
Ok	Engine Access Doors
Ok	Sheet Metal
Ok	Tandem Axles
Ok	(Blade Tilt Frame (saddle
Ok	Circle Wear Strips
Ok	Circle Gear Box
Ok	Articulating Centre Pins Wear
Ok	Front Axle Oscillating Pin Wear
Ok	Wheel Tilt Linkage
Ok	Main Blade
Ok	Ground Ripper



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Need replace

Ok

Batteries

Frame Stamp Serial Number

Hydraulic System

Pump minor leak

Ok

Ok, minor leak and sound

Ok

Ok

Ok

Ok

Ok

Ok

Ok

Hydraulic Leaks

Rotating Gear Drive

Hydraulic Control Valves

Hydraulic Pumps

Saddle Positioning Cylinder

Steering Hydraulic Cylinders

Blade Cylinders/ Angle, lift, side

Ripper Hydraulic Cylinders

Articulation Hydraulic Cylinders

Tires lean cylinder

Limited Functional Testing & Operation

Functional

Ok

Need minor service

Functional

Functional

Need minor service

Functional

Functional

Functional

Functional

Functional

Functional

Functional

Gear Shifting Test

Tandem Axle Noise Check

Brake System Test

Steering Function Test

Tires Lean Function Test

Electrical System Check

Blade Attachment Pins

Blade Side Movement Shifting

Rotating Circle Movement Check

Front Blade Function Test

Ripper & Scarifier Function Test

Steering Tires Angle Adjustment

Clutch Operation Test

Tires Inspection

30%

30%

40%

Front Right Tire

Front Left Tire

Center Right Tire



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Damaged, need change

30%

70%

Center Left Tire

Rear Right Tire

Rear Left Tire

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

