

PLANT & EQUIPMENT

تقرير الفحص – 2014 تاتا دايو M9AVF

الرقم التسلسلي: KL3M9AVF1EK000608 | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١١١٢

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Shift
N/A	Semi-Automatic
N/A	Cruise Control
N/A	Cabin Refrigerator
N/A	(Emissions Status (Add blue
N/A	Hill stand aid function
N/A	Horn off-on
N/A	Tachograph
N/A	Auto Lube
Not cooling	A/C
N/A	Navigation
Yes	ABS
Yes	Driver bed
N/A	Moving off aid
N/A	Lane departure warning system
N/A	Extended Fuel tank
Yes	Retarder
N/A	Rear Axle Lifter
N/A	Radio
N/A	TRC
N/A	Camera sensor
Yes	Differential lock
Yes	Advanced emergency brake assist
Yes	Water Tank

Truck Cabin Details

Need upholstery	Seat and Arm Support
Need service door lock need repair	Cab Doors & covers



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Need service	Controls, Levers
Ok	Windows and Mirrors
Not functional	Dashboard Screen, Gauges
Not functional	Warning alarms message
Not functional	Washer, Wipers
Not cooling	Air Conditioning & Heating System
Need minor service	Cab Floor Covering
Ok	Interior, Covers
Need upholstery	Passenger Seat
N/A	Radio
Need minor service	Electrical System

Engine & Performance

Mechanical	Fuel Injection Type
DV15TIS	Engine Model
Radiator broken	Engine Cooling System
Ok	Engine Oil Check
Normal	Blowby
Ok, minor welding	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
N/A, radiator broken	Coolant
Minor leak from engine head, oil sump	Fluid Leaks
Direct from starter	Starting

Exterior Condition & Visual Inspection

Ok, minor rust	Chassis, Frames
Ok	Frame Stamp Serial Number
Ok	Sheet Metal, Covers
Ok, need minor service	Steps, Grab Irons
Ok	Paintwork
Ok	Cooler Grill
Front bumper need replace	Bumpers
Front signal lights missing, need 4 bulbs	Lights / Batteries



PLANT & EQUIPMENT

Ok	Fenders
Ok, front and rear spring leafs minor loose	Suspension Springs/Hangers
Ok	Suspension Bushings
Ok	Water Tank

Power Train

Ok	Axels/Differentials
Ok, minor loose	Stabilizers, Beams
Ok	Rubber Sleeves
Ok	Brake Pads/Disks
Ok, minor leak	Compressor
Ok	Transfer Gear
Ok	Universal Joints
Normal	Transmission
Ok	Clutch

Truck Limited Functional Test

Ok	Transmission Forward
Ok	Transmission Reverse
Ok	Steering
N/A	Automatic Group Select
Ok	Service Brake
Ok	Park Brake
Need service	Electrics
Ok	Retarder

hydraulics

N/A	PTO Pump
Not tested	Water pump
Not functional, leaks	cabine lift cylinder & valve

Tires

L70%, R70%	(%) Axle 1 / RHS (%) / LHS
L60%, R 70%	(%) Axle 2 / RHS (%) / LHS



PLANT & EQUIPMENT

L60%, R30%

L50%, R40%

L70%, R40%

L70%, R30%

315/80 R22.5

(%) Axle 3 Inside / RHS (%) / LHS

(%) Axle 3 Outside / RHS (%) / LHS

(%) Axle 4 Inside / RHS (%) / LHS

(%) Axle 4 Outside / RHS (%) / LHS

Tire Size

Water Tank

5000 galon

Ok, minor dent

size

condition

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com