

PLANT & EQUIPMENT

تقرير الفحص – 2014 تاتا دايو M9AVF

الرقم التسلسلي: KL3M9AVF1EK000613 | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١١١١

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Shift
N/A	Semi-Automatic
N/A	Cruise Control
N/A	Cabin Refrigerator
N/A	(Emissions Status (Add blue
Yes	Hill stand aid function
N/A	Horn off-on
N/A	Tachograph
N/A	Auto Lube
N/A	A/C
N/A	Navigation
Yes	ABS
Yes	Driver bed
N/A	Moving off aid
N/A	Lane departure warning system
N/A	Extended Fuel tank
Yes	Retarder
N/A	Rear Axle Lifter
N/A	Radio
N/A	TRC
N/A	Camera sensor
Yes	Differential lock
Yes	Advanced emergency brake assist
Yes	Water Tank

Truck Cabin Details

Need upholstery	Seat and Arm Support
Need service	Cab Doors & covers



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

Need service	Controls, Levers
2 mirrors glass broken, front glass cracked, driver blind spot window cracked	Windows and Mirrors
Not functional	Dashboard Screen, Gauges
Not functional	Warning alarms message
Not functional	Washer, Wipers
Not cooling	Air Conditioning & Heating System
Need service	Cab Floor Covering
Need service	Interior, Covers
Need upholstery	Passenger Seat
N/A	Radio
Need service, starts direct from starter, switch off from fuel bump switch	Electrical System

Engine & Performance

Mechanical	Fuel Injection Type
DV15TIS	Engine Model
Ok	Engine Cooling System
Ok, need change	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Ok	Coolant
Minor from oil sump, side cover	Fluid Leaks
Direct from starter	Starting

Exterior Condition & Visual Inspection

Ok, minor rust	Chassis, Frames
Ok	Frame Stamp Serial Number
Ok	Sheet Metal, Covers
Ok, need service	Steps, Grab Irons
Ok	Paintwork
Ok	Cooler Grill



PLANT & EQUIPMENT

Front bumper need repair
Front signal light missing, need 4 bulbs
Ok
Front and rear springs minor loose
Front bushes need replace
Ok

Bumpers
Lights / Batteries
Fenders
Suspension Springs/Hangers
Suspension Bushings
Water Tank

Power Train

Ok
Spring leafs minor loose
N/A
Ok
Ok, minor leak
Ok
Ok, minor loose
Ok, manual
Ok

Axels/Differentials
Stabilizers, Beams
Rubber Sleeves
Brake Pads/Disks
Compressor
Transfer Gear
Universal Joints
Transmission
Clutch

Truck Limited Functional Test

Ok
Ok
Ok
N/A
Ok
Ok
Need minor service
Ok

Transmission Forward
Transmission Reverse
Steering
Automatic Group Select
Service Brake
Park Brake
Electrics
Retarder

hydraulics

N/A
Not tested
Not functional, Jack leaks

PTO Pump
Water pump
cabine lift cylinder & valve

Tires



PLANT & EQUIPMENT

R50%, L70%

(%) Axle 1 / RHS (%) / LHS

R10%, L50%

(%) Axle 2 / RHS (%) / LHS

R40%, L no tire

(%) Axle 3 Inside / RHS (%) / LHS

R40%, L no tire

(%) Axle 3 Outside / RHS (%) / LHS

R70%, L 60%

(%) Axle 4 Inside / RHS (%) / LHS

R10%, L 40%

(%) Axle 4 Outside / RHS (%) / LHS

-

Tire Size

Water Tank

5000 gallon

size

Ok

condition

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com