

تقرير الفحص – 2015 كاتربيلر 966H

الرقم التسلسلي: CAT0966HJBJ601493 | ساعات: ٢٧٤٤٤ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ١٠١٩

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Lubrication System
N/A	Auxiliary Hydraulic Valve
N/A	Equipment Parts Manual
Ok	Air Conditioning System
N/A	(Hydrostatic Drive System (Hydrostat
Ok	Supplemental Steering System
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Quick Attachment Coupler
N/A	Load Weighing System
Ok	Horn Function

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Controls, Levers
Ok	Windows and Mirrors
Ok	Dashboard Screen, Gauges
96-3, 351-13, 274-3	Warning alarms message
Ok, rear wiper missing	Washer, Wipers
Ok	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
Need minor service	Electrical System

Engine & Performance

Electronic	Fuel Injection Type
------------	---------------------



C11	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Normal water	Coolant
Minor leaks	Fluid Leaks

Exterior Condition & Visual Inspection

Ok	Main Frame and Lift Arm
Ok	Engine Hood
Ok	Access Steps and Handrails
Ok	Exterior Paint Condition
Ok	Counterweight Condition
Ok	Wheel Fenders
Ok	Lights Check
Ok	Battery Check
Engine left cover missing	Covers

Power Train Inspection

Ok	Axles and Differentials
Minor oil leak	Transmission Gearbox
Ok	Power Train force
Ok	Transmission Noise Check
Ok	Universal Joint Condition
Semi- auto	Transfer Gear Type

Hydraulic System

OK, minor leaks	Hydraulic Leaks
Ok, minor leak	Lift and Tilt Hydraulic Jack
Ok, minor leak	Steering Hydraulic Jacks
Ok	Hydraulic Pumps and Valves



Limited Functional Testing & Operation

Ok	Steering Function Test
OK, 2nd front gear not functional	Transmission Operation Test
Ok	Loader Stall Test
Ok	Brake System Test
Ok	Articulation Movement Check
Ok, bucket pins minor loose	Loader Attachment Pins

Attachments

W3200, H1500, D1000 mm	Bucket Width and Capacity
Minor Damaged	Bucket Bottom Condition
Ok, no teeth	Bucket Edge & Teeth Condition
Ok	Bucket Side Condition
Ok	Attachment Coupler

Tires Inspection

-	Front Right
MAXAM, 26.5R25	Tire Brand & Size Details
70%	Tire Remaining Life Percentage
Good, Tubeless	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Front Left
ITR, 26.5R25	Tire Brand & Size Details
50%	Tire Remaining Life Percentage
Good, Tubeless	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Right
MAXAM, 26.5R25	Tire Brand & Size Details
70%	Tire Remaining Life Percentage
Good, Tubeless	Tire Condition Notes
Ok	Wheel Rims & Nuts
-	Rear Left
Advance 26.5R25	Tire Brand & Size Details



70%
Good, Tubeless
Ok

Tire Remaining Life Percentage
Tire Condition Notes
Wheel Rims & Nuts

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

