

تقرير الفحص – 2015 كاتربيلر D6R XL

الرقم التسلسلي: CAT00D6RAJEN00313 | ساعات: ١٥٨٧٤ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٩٠٩

Key Features & Condition

N/A	Safety Certification Label
N/A	Ground Ripper
N/A	Ripper Control Valve
N/A	Low Ground Pressure Tracks
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Grade Control System
N/A	Equipment Parts Manual
N/A	CAT System One
N/A	Horn

Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Controls, Levers
Ok	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
Ok	Washer, Wipers
Not Functional	Air Conditioning & Heating System
N/A	Cab Floor Covering
N/A	Cab Structure, Gard
Ok, need minor service (Engine RPM)	Electrical System

Engine & Performance

Electronic	Fuel Injection Type
C9	Engine Model
Ok	Engine Cooling System



Ok	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok, filters need change	Belts & Air/Oil Filters
Minor	Smoke
Ok, normal water	Coolant
Ok, minor gasket leak	Fluid Leaks
Need minor service	Fuel System

Exterior Condition & Visual Inspection

Ok	Push Frame & Trunnions
Ok	Doors, Covers, and Grilles
Ok	Access Steps & Handrails
Ok	Exterior Paint Condition
Ok	Blade Trunnions & Bushings
Ok	Underbody Protection Plates
Functional	Final Drive Condition
Ok	Fuel Tank, Roof, & Hood Condition
Need battery and terminals, rear lights missing	Lights and Battery Check
Ok	Push Arm Pivot Shaft
Ok	Tilt Linkage Pins & Bushings

Hydraulic System

Ok	Hydraulic Leaks
Ok	Lift Hydraulic Jacks
N/A	Ripper Lift Hydraulic Jacks
Ok	Tilt Hydraulic Jack
N/A	Angle Hydraulic Jack
N/A	Ripper Angle Hydraulic Jacks

Limited Functional Testing & Operation

Ok	Push Frame Pins
Ok	Blade Pins
N/A	Ripper Pins



Ok	Equalizer Bar Condition
Ok	Bulldozer Stall Test
Ok	Steering Function Test
Ok	Blade Tilt and Lift Test
Ok	Undercarriage Pivot Pins
Functional	Transmission Test
Ok	Brake System Test
Functional	Torque Converter Test

Blade Inspection

Ok	Blade Base Condition
Ok	Spill Rack Condition
Ok	Blade Front Condition
Ok	Blade Edge Condition

Undercarriage Inspection

-	Right Side Undercarriage Wear
80%	Undercarriage Bushings
70%	Undercarriage Shoes
90%	Front Idler Condition
90%	Rear Idler Condition
90%	Carrier Roller Condition
90%	Track Links Condition
90%	Sprocket Condition
90%	Roller Condition
70%	Track Canon Condition
-	Left Side Undercarriage Wear
80%	Undercarriage Bushings
70%	Undercarriage Shoes
90%	Front Idler Condition
90%	Rear Idler Condition
90%	Carrier Roller Condition
90%	Track Links Condition
90%	Sprocket Condition



المعدات والآليات | تقويم المزادات

90%

70%

W560, L230 mm

Roller Condition

Track Canon Condition

Track Width Measurement

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

