

PLANT & EQUIPMENT

تقرير الفحص – 2015 دووسان DL420A

الرقم التسلسلي: DWGCWLBEBF1010799 | الموقع: Dubai, الإمارات العربية المتحدة | رقم التعريف: ١١٧٣

Key Features & Condition

N/A	Safety Certification Label
N/A	Automatic Lubrication System
N/A	Auxiliary Hydraulic Valve
N/A	Equipment Parts Manual
N/A	Air Conditioning System
N/A	(Hydrostatic Drive System (Hydrostat
N/A	Supplemental Steering System
N/A	Operator's Manual
N/A	Emission Compliance Label
N/A	Quick Attachment Coupler
N/A	Load Weighing System
N/A	Horn Function

Operator Cabin Details

Need upholstery	Seat and Arm Support
Need service	Cab Doors & covers
Need service	Controls, Levers
Ok	Windows and Mirrors
Need minor service, only rpm gauge functional	Dashboard Screen, Gauges
Screen need service	Warning alarms message
Not functional	Washer, Wipers
Not functional	Air Conditioning & Heating System
Need minor service	Cab Floor Covering
Ok	Cab Structure, Gard
Need service	Electrical System
Direct from fuel pump	Shut off

Engine & Performance

Mechanical	Fuel Injection Type
------------	---------------------



شركة باندي لمزادات ش.ذ.م.م

دبي، صندوق بريد: 71530، دبي، الإمارات العربية المتحدة

هاتف: +97148861125

www.PlantAndEquipment.com

PLANT & EQUIPMENT

DE12TIA	Engine Model
Ok	Engine Cooling System
Ok, need change	Engine Oil Check
Normal	Blowby
Ok, minor welded	Exhaust System & Muffler
Need change	Belts & Air/Oil Filters
Normal	Smoke
Ok	Coolant
Filter housing minor leak, oil sump	Fluid Leaks

Exterior Condition & Visual Inspection

Ok	Main Frame and Lift Arm
Need minor service	Engine Hood
Ok	Access Steps and Handrails
Ok, repainted	Exterior Paint Condition
Ok	Counterweight Condition
Ok	Wheel Fenders
Need 2 bulbs	Lights Check
Need replace	Battery Check
Ok	Covers

Power Train Inspection

Rear left axle minor leak, front and rear differentials leaks	Axles and Differentials
Minor Oil Leak	Transmission Gearbox
Ok	Power Train force
Ok	Transmission Noise Check
Ok, minor loose	Universal Joint Condition
Semi- auto	Transfer Gear Type

Hydraulic System

Ok, minor meak	Hydraulic Leaks
Ok, lift jack minor meak	Lift and Tilt Hydraulic Jack
N/A	Steering Hydraulic Orbital



PLANT & EQUIPMENT

Ok, minor meak
Ok, valves minor leak

Steering Hydraulic Jacks
Hydraulic Pumps and Valves

Limited Functional Testing & Operation

Functional
Functional
Functional
Functional
Functional
Ok

Steering Function Test
Transmission Operation Test
Loader Stall Test
Brake System Test
Articulation Movement Check
Loader Attachment Pins

Attachments

w3090, H1360, D910 mm
Ok
Ok
Ok
Ok

Bucket Width and Capacity
Bucket Bottom Condition
Bucket Edge & Teeth Condition
Bucket Side Condition
Attachment Coupler

Tires Inspection

-
HUNG - A 26.5 - 25
70%
Ok
Ok
-
DEES STONE 26.5 - 25
60%
Ok
Ok
-
POWER GT 26.5 - 25
60%
Ok
Ok

Front Right
Tire Brand & Size Details
Tire Remaining Life Percentage
Tire Condition Notes
Wheel Rims & Nuts
Front Left
Tire Brand & Size Details
Tire Remaining Life Percentage
Tire Condition Notes
Wheel Rims & Nuts
Rear Right
Tire Brand & Size Details
Tire Remaining Life Percentage
Tire Condition Notes
Wheel Rims & Nuts



PLANT & EQUIPMENT

-	Rear Left
TIRON 26.5 - 25	Tire Brand & Size Details
60%	Tire Remaining Life Percentage
Ok	Tire Condition Notes
Ok	Wheel Rims & Nuts

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

