

## تقرير الفحص – 2015 كوماتسو PC450LC-8

الرقم التسلسلي: KMTPC192H02070013 | ساعات: ٦١٥٥ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٦٨٤

### Key Features & Condition

N/A	Safety Certification Label
Yes	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
Yes	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
Yes	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
Ok	Horn

### Operator Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, mirrors are missing	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning alarms message
Ok	Washer, Wipers
Ok	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
Ok	Electrical System

### Engine & Performance

Electronic	Fuel Injection System
SAA6D125E-5	Engine Model



Ok	Engine Cooling System
Ok	Engine Oil Check
Ok	Cooling System
Ok, normal water	Coolant
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Ok	Leaks & Seals

## Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
Missing	Lights
Ok	Battery Check
Ok	Cabin Compartments
Ok, repainted	Exterior Paint Condition

## Hydraulic System

Ok	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Ok	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

## Performance analysis

Ok	Boom Pins Condition
Ok	Excavator self- Drift Test



Ok	Arm Pins Condition
Ok	Hydraulic Pump Noise Check
Ok	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok	Swing Drive and Brake Test
Ok	Drive force Test

## Attachments

Bucket	Attachments model
W1500, H1200, D90 mm	Size
Ok	Status
Ok	Coupler status
N/A	Second Attachments model
N/A	Size
N/A	Status

## Undercarriage

0.7	bushings
0.8	Track shoes
0.8	idlers
mm 600	:shoe width in mm
mm 75	:track pitch in mm
0.7	carrier rollers
0.7	Track rollers
0.7	Track links
0.7	Sprocket segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

