

## تقرير الفحص – 2017 كاتربيلر 980L

الرقم التسلسلي: CAT0980LCD8Z10264 | ساعات: ٢٠٥٦٧ | الموقع: دبي, الإمارات العربية المتحدة | رقم التعريف: ٧٧٣

### Key Features & Condition

|     |                                      |
|-----|--------------------------------------|
| N/A | Safety Certification Label           |
| N/A | Automatic Lubrication System         |
| N/A | Auxiliary Hydraulic Valve            |
| N/A | Equipment Parts Manual               |
| Yes | Air Conditioning System              |
| N/A | (Hydrostatic Drive System (Hydrostat |
| Yes | Supplemental Steering System         |
| N/A | Operator's Manual                    |
| N/A | Emission Compliance Label            |
| N/A | Quick Attachment Coupler             |
| N/A | Load Weighing System                 |
| Yes | Horn Function                        |

### Operator Cabin Details

|  |                                   |
|--|-----------------------------------|
| Ok   | Seat and Arm Support              |
| Ok   | Cab Doors & covers                |
| Ok   | Controls, Levers                  |
| Ok   | Windows and Mirrors               |
| Ok   | Dashboard Screen, Gauges          |
| Implement calibration, fuel water sperator is full | Warning alarms message            |
| Ok, rear wiper is not functional                   | Washer, Wipers                    |
| Ok   | Air Conditioning & Heating System |
| Ok   | Cab Floor Covering                |
| Ok,no Guard  | Cab Structure, Guard              |
| Ok   | Electrical System                 |

### Engine & Performance



|            |                          |
|------------|--------------------------|
| Electronic | Fuel Injection Type      |
| C13        | Engine Model             |
| Ok         | Engine Cooling System    |
| Ok         | Engine Oil Check         |
| Normal     | Blowby                   |
| Ok         | Exhaust System & Muffler |
| Ok         | Belts & Air/Oil Filters  |
| Normal     | Smoke                    |
| Ok         | Coolant                  |
| Ok         | Fluid Leaks              |

## Exterior Condition & Visual Inspection

|                                  |                            |
|----------------------------------|----------------------------|
| Ok                               | Main Frame and Lift Arm    |
| Ok                               | Engine Hood                |
| Ok, first step is missing        | Access Steps and Handrails |
| Ok                               | Exterior Paint Condition   |
| Ok                               | Counterweight Condition    |
| Ok                               | Wheel Fenders              |
| Ok, need 3 bulbs                 | Lights Check               |
| Ok                               | Battery Check              |
| missing covers, 1-missing door-2 | Side Doors & Covers        |

## Power Train Inspection

|                                   |                           |
|-----------------------------------|---------------------------|
| Ok                                | Axles and Differentials   |
| Ok, second gear is not functional | Transmission Gearbox      |
| Ok                                | Power Train force         |
| Ok                                | Transmission Noise Check  |
| Ok                                | Universal Joint Condition |
| Semi-Auto                         | Transfer Gear Type        |

## Hydraulic System

|    |                              |
|----|------------------------------|
| Ok | Hydraulic Leaks              |
| Ok | Lift and Tilt Hydraulic Jack |
| Ok | Steering Hydraulic Orbital   |



Ok

Steering Hydraulic Jacks

Ok

Hydraulic Pumps and Valves

## Limited Functional Testing & Operation

Ok

Steering Function Test

Ok, second gear is not operational

Transmission Operation Test

Ok

Loader Stall Test

Ok

Brake System Test

Ok

Articulation Movement Check

Ok

Loader Attachment Pins

Ok

Supplemental Steering Test

## Attachments

(W3350, H1500, D1250 (5.7 m<sup>3</sup>

Bucket Width and Capacity

Ok, armored

Bucket Bottom Condition

Ok

Bucket Edge & Teeth Condition

Ok

Bucket Side Condition

Ok

Attachment Coupler

## Tires Inspection

-

Front Right

(BKT (29.5R25

Tire Brand & Size Details

70%

Tire Remaining Life Percentage

Ok, tiny cuts

Tire Condition Notes

Ok

Wheel Rims & Nuts

-

Front Left

(BKT (29.5R25

Tire Brand & Size Details

30%

Tire Remaining Life Percentage

Some wears, cuts

Tire Condition Notes

Ok

Wheel Rims & Nuts

-

Rear Right

(BKT (29.5R25

Tire Brand & Size Details

80%

Tire Remaining Life Percentage

Ok

Tire Condition Notes



Ok, 1-nut is missing

-

(BKT (29.5R25

40%

Minor wears, cuts

Ok

Wheel Rims & Nuts

Rear Left

Tire Brand & Size Details

Tire Remaining Life Percentage

Tire Condition Notes

Wheel Rims & Nuts

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

