

تقرير الفحص – 2018 مرسيدس بنز Actros 1845

الرقم التسلسلي: WDB96340310246651 | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٧٦٣

Key Features & Condition

Yes	Safety Certification Label
Yes	Automatic Shift
Yes	Semi-Automatic
Yes	Cruise Control
N/A	Cabin Refrigerator
Yes	Add Blue
Yes	Hill Stand Aid Function
Yes	Horn Off-On
Yes	Tachograph
N/A	Auto Lube
Yes	A/C
N/A	Navigation
N/A	ABS
Yes	Driver Bed
Yes	Moving Off Aid
Yes	Lane Departure Warning System
N/A	Extended Fuel Tank
Yes	Retarder
Yes	Rear Axle Lifter
Yes	Radio
N/A	TRC
N/A	Camera Sensor
Yes	Differential Lock
N/A	Advanced Emergency Brake Assist

Truck Cabin Details

Ok	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Controls, Levers



Ok	Windows and Mirrors
Ok	Dashboard Screen, Gauges
Ok, The transmission's/braking common lever is faulty, A malfunction in the exhaust gas treatment system	Warning alarms message
Ok	Washer, Wipers
Ok	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Interior, Covers
Ok	Passenger Seat
Ok	Radio

Engine & Performance

Electronic	Fuel Injection Type
M3B Eng. OM471, inline 6, 12.8 l, 330kW (449hp), 2200 Nm	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Normal	Blowby
Ok	Exhaust System & Muffler
Ok	Belts & Air/Oil Filters
Normal	Smoke
Ok, normal water	Coolant
Ok	Fluid Leaks

Exterior Condition & Visual Inspection

Ok	Chassis, Frames
Ok	Sheet Metal, Covers
Ok	Steps, Grab Irons
Ok	Paintwork
Ok	Cooler Grill
Ok, side minor crack	Bumpers
Ok	Lights / Batteries
Ok	Fenders



Power Train

Ok	Axels/Differentials
Ok	Stabilizers, Beams
Ok	Rubber Sleeves
Ok	Brake Pads/Disks
Ok	Compressor
(Ok, late response (alarm message	Transfer Gear
Ok	Universal Joints
Ok	Transmission
N/A	Clutch

Truck Limited Functional Test

Ok	Transmission Forward
Ok	Transmission Reverse
Ok	Automatic Group Select
Ok	Service Brake
Ok	Park Brake
Ok	Electrics
Ok	Retarder

Tires

Out of date 70% / 70%	(%) Axle 1 / RHS mm (%) / LHS mm
Out of date 40% / 30%	(%) Axle 2 Inside / RHS mm (%) / LHS mm
Out of date 40% / 30%	(%) Axle 2 Outside / RHS mm (%) / LHS mm
(80R22.5) 315	Tire Size

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

