

تقرير الفحص – 2019 كوماتسو PC400LC-8R

الرقم التسلسلي: KMTPC196TJXJ31260 | ساعات: ٢٠٣١٢ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١٠٣٢

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
N/A	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
N/A	Hydraulic Hammer Lines
N/A	Grapple and Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System AddBlue
N/A	Stabilizer Blade Condition
N/A	Horn

Operator Cabin Details

Need upholstery	Seat and Arm Support
Ok	Cab Doors & covers
Ok	Control Levers, Control Stick
Ok, 1 broken mirror	Windows and Mirrors
OK, hard visual protection glass scratched	Dashboard Screen, Gauges
abnormal drop in coolant level (sensor need replace)	Warning alarms message
Not functional	Washer, Wipers
Not cooling	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure
Need minor service	Electrical System

Engine & Performance

Electrical	Fuel Injection System
------------	-----------------------



Komatsu-saa6d125e-5	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Ok	Cooling System
Normal water	Coolant
Normal	Exhaust System & Muffler
Ok, filters need change	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Ok	Leaks & Seals

Exterior Condition & Visual Inspection

Ok, main frame minor dents	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps and Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
need 2 bulbs	Lights
Ok	Battery Check
Ok	Cabin Compartments
Ok	Exterior Paint Condition

Hydraulic System

Ok, minor leaks	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Ok, pump minor leak	Hydraulic Pump & Valve Block
Minor leak	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

Performance analysis

Ok	Boom Pins Condition
----	---------------------



Functional
Minor loose
Ok, minor
Minor loose
Minor loose
Functional
Ok

Excavator self- Drift Test
Arm Pins Condition
Hydraulic Pump Noise Check
Bucket Pins Condition
Swing Ring Bearing Movement Check
Swing Drive and Brake Test
Drive force Test

Attachments

Bucket with teeth
W 1750, D 1100, H 1800
Ok
Ok
N/A
N/A
N/A

Attachments model
Size
Status
Coupler status
Second Attachments model
Size
Status

Undercarriage

R 50% L 60%
70%
70%
600
80
70%
70%
60%
R 60% L 40%

bushings
Track shoes
idlers
:shoe width in mm
:track pitch in mm
carrier rollers
Track rollers
Track links
Sprocket segments

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

