

## تقرير الفحص – 2023 اكس سي ام جي XCT80

الرقم التسلسلي: LXGCPA508PA003739 | كم: ٧٤٠٨ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ٨٥٤

### Key Features & Condition

N/A	CE Labeling
N/A	Automatic Shift
N/A	Semi-Automatic
N/A	Tachograph
N/A	Auto Lube
N/A	A/C
N/A	Extended Fuel tank
N/A	Retarder
N/A	Rear Axle Lifter
Yes	Axle Steering 2

### Truck Cab

Ok	Driver Seat
Ok	Switches, Levers
Gauges functional, screen is not functional	Gauges, Warn Lights
Not cooling	Aircon / Heater
Ok	Passenger Seat
Ok	Cab Doors
Ok, right small mirror cracked	Windows, Mirrors
Ok	Wipers, Washers
Ok	Interior, Covers
Ok	Radio

### Crane operator cab

Ok	Driver Seat
Ok	Switches, Levers
Ok	Gauges, Warn Lights
N/A	Aircon / Heater



Ok	Cab Doors
Ok	Windows
Ok	Wipers
Ok	Interior Covers

## Engine

Electronic	Injection Type
wp12.375e50	Engine Model
Ok	Leaks, Seals
Ok	Oil Condition
Ok	Exhaust/Muffler
Ok	Cooling System
Normal	Smoke, Fume
Normal	Blow By
Ok	Belts, Pulleys
Ok, normal water	Coolant Condition

## Visual inspection exterior

Ok, minor welding	Chassis, Frames
Ok	Sheet Metal, Covers
Ok	Steps, Grab Irons
Ok, repainted	Paintwork
Ok	Cooler Grill
Ok	Bumpers
Ok	Lights

## Power Train

Ok	Axels/Differentials
Ok	Stabilizers, Beams
Wear-Out	Rubber Sleeves
Ok	Brake Pads/Disks
Functional	Compressor
Manual, need minor service	Transfer Gear
Ok	Universal Joints



Functional  
Need service

Transmission  
Clutch

## Hydraulics / Steering

Ok  
Ok  
Ok  
Ok  
Ok

Hoses & Lines  
Hydraulic Pump  
PTO  
Steering Cylinders  
Steering Linkage

## Carrier Limited Functional Test

Functional hard gear shift  
Functional hard gear shift  
N/A  
Functional  
Functional  
Functional  
Not tested

Transmission Forward  
Transmission Reverse  
Automatic Group Select  
Service Brake  
Park Brake  
Electrics  
Retarder

## Crane Condition / Limited Test

Functional  
Ok  
Ok  
Ok  
Functional  
Ok  
Not functional  
Ok  
Functional

Controls, Levers  
Boom Conditions  
Telescopic Segments  
Hydraulic Cylinders  
Swing Bearing / Drive  
Hose Lines  
Lift Limitations  
Hook  
Outriggers

## % Tires Condition

-  
60%  
50%

Right  
Axle 1  
Axle 2 Inside



# المعدات والآليات | تقويم المزادات

70% (2019 Need change)	Axle 3 Outside
70% (2019 Need change)	Axle 3 Inside
60% (2019 Need change)	Axle 4 Outside
60% (2019 Need change)	Axle 4 Inside
-	Left
60%	Axle 1
50%	Axle 2 Inside
60% (2019 Need change)	Axle 3 Outside
60% (2019 Need change)	Axle 3 Inside
60% (2019 Need change)	Axle 4 Outside
40% (2019 Need change)	Axle 4 Inside

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

