

تقرير الفحص – 2018 كاتربيلر 330D2L

ساعات: ١٣١٦٢.٠ | الموقع: دبي، الإمارات العربية المتحدة | رقم التعريف: ١٣٢٠٥٦١

Key Features & Condition

N/A	Safety Certification Label
N/A	Boom Hydraulic Check Valve
N/A	Adjustable Boom System
Yes	Automatic Lubrication System
N/A	Arm Hydraulic Check Valve
N/A	Diesel Particulate Filter
N/A	Hydraulic Hammer Lines
N/A	Grapple And Shear Hydraulic Lines
N/A	Diesel Exhaust Fluid System Addblue
N/A	Stabilizer Blade Condition
N/A	Horn
Yes	Fire Fiting System

Operator Cabin Details

Ok	Seat And Arm Support
Ok	Cab Doors & Covers
Ok	Control Levers, Control Stick
Ok, front window is cracked,1- mirror is missing	Windows And Mirrors
Ok	Dashboard Screen, Gauges
Ok	Warning Alarms Message
Ok	Washer, Wipers
Ok	Air Conditioning & Heating System
Ok	Cab Floor Covering
Ok	Cab Structure, Gard
Ok	Electrical System

Engine & Performance

Electronic	Fuel Injection System
------------	-----------------------



™Cat® C7.1 ACERT	Engine Model
Ok	Engine Cooling System
Ok	Engine Oil Check
Ok	Cooling System
Ok, normal water	Coolant
Ok	Exhaust System & Muffler
Ok, belt need change	Belts & Air/Oil Filters
Normal	Smoke Check
Normal	Blowby
Ok	Leaks & Seals

Exterior Condition & Visual Inspection

Ok	Main Frame & Track Frame
Ok	Protective Covers & Sheets
Ok	Engine Hood
Ok	Side Access Doors
Ok	Steps And Handrails
Ok	Boom Condition
Ok	Bumpers & Catwalk Condition
Ok	Arm Condition
Ok	Lights
Need change	Battery Check
Ok	Cabin Compartments
Ok	Exterior Paint Condition

Hydraulic System

Ok	Hydraulic Leaks
Ok	Boom Hydraulic Jack
Ok	Hydraulic Pump & Valve Block
Ok	Bucket Hydraulic Jack
Ok	Arm Hydraulic Jack

Performance analysis

Ok, 1 pin minor loose	Boom Pins Condition
-----------------------	---------------------



المعدات والآليات | تقويم المزادات

Ok	Excavator Self- Drift Test
Ok	Arm Pins Condition
Ok	Hydraulic Pump Noise Check
Ok, minor loose	Bucket Pins Condition
Ok	Slewing Ring Bearing Movement Check
Ok	Swing Drive And Brake Test
Ok	Drive Force Test

Attachments

Bucket	Attachments Model
W1650, H700, D1000 mm	Size
Ok	Status
Ok	Coupler Status
N/A	Second Attachments Model
N/A	Size
N/A	Status

Undercarriage

70%	Bushings
70%	Track Shoes
80%	Idlers
600	:Shoe Width In Mm
80	:Track Pitch In Mm
70%	Carrier Rollers
70%	Track Rollers
70%	Track Links
80%	Sprocket Segments

يتم تقديم أي ضمانات فيما يتعلق بالساعات الفعلية أو الأميال أو الكيلومترات؛ تقرير الفحص يعكس فقط ما يمكن أن يكون لوحظ بصريا .

