

Inspection report – 2004 Caterpillar M318

Serial No: 8AL02321 | Hours: 28123 | Location: Dubai, United Arab Emirates | SKU: 796

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	Yes
Adjustable Boom System	Yes
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	Yes
Back camera	N/A
Quick Coupler	N/A
Hydraulic Hammer Lines	Yes
Grapple and Shear Hydraulic Lines	Yes
Stabilizer Blade Condition	N/A
Horn	N/A
Schild Plate	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok, no cover and lock need repair
Control Levers, Control Stick	Functional
Windows and Mirrors	Ok, right mirror is missing
Dashboard Screen, Gauges	N/A
Warning alarms message	N/A
Washer, Wipers	N/A
Air Conditioning & Heating System	N/A
Cab Floor Covering	N/A
Cab Structure, Gard	Ok, no guard
Electrical System	Need repair

Engine & Performance

Fuel Injection Type	Mechanical
Engine Model	3116T

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Minor
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Ok, normal water
Leaks& seals	Minor leaks
Battery Alternator	Need repair

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	N/A
Battery Check	N/A
Counterweight	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Minor
Boom Hydraulic Jack	Functional
Hydraulic Pump & Valve Block	Functional
Mono Boom Jack	Functional
Bucket Hydraulic Jack	Functional
Arm Hydraulic Jack	Functional
Pump Noises Check	Normal
Bucket Swing cylinder	N/A

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Transmission & drive train

Transmission Gear	Functional
Axles	Ok
Swivel Joint	Ok
Universal Joint	Ok

Limited Functional Testing & Operation

Boom Pins Condition	Ok, minor loose
Excavator self- Drift Test	Functional , weak
Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Normal
Brack & Parking Brack	Functional
Suspension Lock	Ok
Bucket Pins Condition	Ok
Slewing Ring Bearing Movement Check	Functional
Swing Drive and Brake Test	Functional
Drive force Test	Functional
Slewing Ring Lock	Ok

Attachments

Attachments model	Bucket
Size	W640, H1100, D800 mm
Status	Ok
Coupler status	Ok
Second Attachments model	Schild blade
Size	W2500, H550 mm
Status	Ok

Tires Estimated Remaining Life %

Front Right	30%
Front Left	20%
Rear Right	25%
Rear Left	20%
Size	10.00R20

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Type	Tube (on road)
Spacer Rings	N/A
Damages / Cuts	Minor
Nuts	1 missing

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

