

Inspection report – 2004 Vogele 2116T

Serial No: 30654 | Hours: 7190 | Location: Dubai, United Arab Emirates | SKU: 802

Key Features & Condition

|                              |     |
|------------------------------|-----|
| Safety Certification Label   | N/A |
| Automatic Lubrication System | N/A |
| Auxiliary Hydraulic Valve    | N/A |
| Equipment Parts Manual       | N/A |
| Track Shoes w/Rubber Inserts | Yes |
| Horn Function                | Yes |
| Travel Alarm                 | N/A |
| Operator’s Manual            | N/A |
| Emission Compliance Label    | N/A |

Operator Cabin Details

|                                 |                                 |
|---------------------------------|---------------------------------|
| Seat and Arm Support            | Ok, need upholstery             |
| control levers, Control swithes | Ok                              |
| Dashboard Screen, Gauges        | Ok, 3 gauges are not functional |
| Warning alarms message          | Ok                              |
| Electrical System               | Ok, need minor maintinnance     |

Engine & Performance

|                            |                  |
|----------------------------|------------------|
| Fuel Injection System Type | Mechanical       |
| Fluid Leaks                | Ok               |
| Engine Oil Check           | Ok               |
| Exhaust System and Muffler | Ok               |
| Exhaust Smoke              | Normal           |
| Engine Model Details       | QSB 5.9          |
| Engine Cooling System      | Ok               |
| Engine Blow-by Check       | Normal           |
| Belts and Air/Oil Filters  | Ok               |
| Coolant                    | Ok, normal water |

Exterior Condition & Visual Inspection



|                                     |                                  |
|-------------------------------------|----------------------------------|
| Chassis                             | Ok                               |
| Screed Lift Arms                    | Ok                               |
| Engine Hood                         | Ok                               |
| Stairs, Handrails                   | Ok                               |
| Auger/ Screw Condition              | Minor wear                       |
| Conveyor Drive Chains and Sprockets | Ok                               |
| Push Rollers                        | Ok                               |
| Screed Heaters                      | Not tested                       |
| End Gates                           | Ok, right gate is not functional |
| Paintwork                           | Ok                               |
| Screed Serial Number                | 5140105                          |
| Screed Bottom Plate / Mat           | Ok                               |
| Sheet Metal                         | Ok                               |
| Hopper Wings                        | Ok                               |
| Feed Conveyors                      | Ok                               |
| Screed Slope Adjustment             | Ok                               |
| Lights                              | Ok, need some bulbs              |
| Batteries                           | Ok                               |
| Berm                                | Not functional                   |

---

## Hydraulic System

|                            |                                  |
|----------------------------|----------------------------------|
| Hoses & Lines              | Ok, some fittings minor oil leak |
| Pump And Valve Bloc        | functional                       |
| Hydraulic Motors           | functional                       |
| Screed Lift Cylinders      | functional                       |
| Screed Extension Cylinders | functional                       |
| Hopper Wing Cylinders      | functional                       |
| Screed Tow Point Cylinders | Not functional                   |
| Slop Cylinder              | functional                       |

---

## Limited Functional Testing & Operation

|               |            |
|---------------|------------|
| Drive forward | functional |
| Drive revers  | functional |
| Steering      | functional |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                   |                                                         |
|-------------------|---------------------------------------------------------|
| Hopper Wings      | functional                                              |
| Feed conveyors    | Manual mode is functional , Auto mode is not functional |
| Auger Flight      | Manual mode is functional , Auto mode is not functional |
| Asphalt compactor | N/A                                                     |
| Asphalt Sweeper   | N/A                                                     |

---

## Undercarriage components remaining life (%)

|                                   |                               |
|-----------------------------------|-------------------------------|
| Left Rubber Track Belt Condition  | 60%                           |
| Left Rubber Belt Drive Lugs       | 50%                           |
| Left Grouser Height               | 70%                           |
| Left Track Rollers                | 2 Rollers /20% - 3Rollers 40% |
| Left Idler                        | 60%                           |
| Left Sprocket                     | 20%                           |
| Right Roller Frame                | 70%                           |
| Right Rubber Track Belt Condition | 70%                           |
| Right Rubber Belt Drive Lugs      | 70%                           |
| Right Grouser Height              | 80%                           |
| Right Track Rollers               | 70%                           |
| Right Idler                       | 80%                           |
| Right Sprocket                    | 80%                           |

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

