

Inspection report – 2007 Caterpillar 938G-II

Serial No: CAT09388GARTB03612 | Hours: 49965 | Location: Dubai, United Arab Emirates | SKU: 906

Key Features & Condition

Safety Certification Label	N/A
Automatic Lubrication System	N/A
Auxiliary Hydraulic Valve	N/A
Equipment Parts Manual	N/A
Air Conditioning System	Yes
Hydrostatic Drive System (Hydrostat)	N/A
Supplemental Steering System	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Load Weighing System	N/A
Horn Function	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok, left mirror is missing, and the front glass and left door glass cracked
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	N/A
Cab Structure, Gard	Ok
Electrical System	Ok

Engine & Performance

Fuel Injection Type	Electronic
---------------------	------------

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Model	3126B
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	PI
Smoke	Normal
Coolant	Ok, normal water
Fluid Leaks	Ok
Battery Alternator	Need service

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Engine Hood	Ok, auto-lift not functional
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok
Counterweight Condition	Ok
Wheel Fenders	Ok, no rear fenders
Lights Check	Ok, 2 lights not functional
Battery Check	Need change

Power Train Inspection

Axles and Differentials	Ok
Transmission Gearbox	Ok
Power Train force	Ok
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi- Auto

Hydraulic System

Hydraulic Leaks	Ok
Lift and Tilt Hydraulic Jack	Ok, right lift jack minor oil leaks
Steering Hydraulic Jacks	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Hydraulic Pumps and Valves

Ok

Limited Functional Testing & Operation

Steering Function Test	Functional
Transmission Operation Test	Functional , 4R not functional
Loader Stall Test	Functional
Brake System Test	Functional
Articulation Movement Check	Ok
Loader Attachment Pins	Functional
Electrical System Check	Functional, need minor service
Supplemental Steering Test	N/A

Attachments

Bucket Width and Capacity	W2600, H1200, D900 mm
Bucket Bottom Condition	Ok, extra plate welded
Bucket Edge & Teeth Condition	Ok, no teeth
Bucket Side Condition	Ok
Attachment Coupler	Ok
Bucket Rear Condition	Ok, welded

Tires Inspection

Front Right	-
Tire Brand & Size Details	TRIANGLE 20.5R25
Tire Remaining Life Percentage	60%
Tire Condition Notes	Ok
Wheel Rims & Nuts	Ok
Front Left	-
Tire Brand & Size Details	HANMIX 20.5R25
Tire Remaining Life Percentage	100%
Tire Condition Notes	New
Wheel Rims & Nuts	Ok
Rear Right	-
Tire Brand & Size Details	TRIANGLE 20.5R25
Tire Remaining Life Percentage	50%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Tire Condition Notes	Ok, minor cut
Wheel Rims & Nuts	Ok
Rear Left	-
Tire Brand & Size Details	TRIANGLE 20.5R25
Tire Remaining Life Percentage	60%
Tire Condition Notes	Ok, minor cut
Wheel Rims & Nuts	Ok

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

