

Inspection report – 2008 Hyundai HL770-7A

Serial No: LB0411043 | Location: Dubai, United Arab Emirates | SKU: 988

Key Features & Condition

Safety Certification Label	N/A
Automatic Lubrication System	N/A
Auxiliary Hydraulic Valve	N/A
Equipment Parts Manual	N/A
Air Conditioning System	Yes
Hydrostatic Drive System (Hydrostat)	N/A
Supplemental Steering System	Yes
Operator's Manual	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Load Weighing System	N/A
Horn Function	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Functional, need minor service
Windows and Mirrors	Ok, left centr mirror is missing
Dashboard Screen, Gauges	Ok, screen not functional
Warning alarms message	Gear box warning
Washer, Wipers	Ok
Air Conditioning & Heating System	Ok
Cab Floor Covering	N/A
Cab Structure	Ok
Electrical System	Need minor service

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	Cummins SQL

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Cooling System	Ok
Engine Oil Check	Ok, need change
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Minor
Coolant	Ok, normal water
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok, Fully repainted
Counterweight Condition	Ok
Wheel Fenders	Ok, no rear fenders
Lights Check	Not functional
Battery Check	Need change

Power Train Inspection

Axles and Differentials	Ok
Transmission Gearbox	Ok
Power Train force	Ok
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi-auto

Hydraulic System

Hydraulic Leaks	Minor oil leaks from Fittings
Lift and Tilt Hydraulic Jack	Ok
Steering Hydraulic Orbital	Ok
Steering Hydraulic Jacks	Ok, minor oil leaks
Hydraulic Pumps and Valves	Functional

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Limited Functional Testing & Operation

Steering Function Test	Functional
Transmission Operation Test	Functional
Loader Stall Test	Functional
Brake System Test	Functional
Articulation Movement Check	Functional
Loader Attachment Pins	Ok, tilt pin minor loose
Supplemental Steering Test	N/A

Attachments

Bucket Width and Capacity	W3000, H1500, D1100 mm
Bucket Bottom Condition	Ok, minor welding
Bucket Edge & Teeth Condition	Ok
Bucket Side Condition	Ok
Attachment Coupler	Ok

Tires Inspection

Front Right	-
Tire Brand & Size Details	MARF 26.5-25
Tire Remaining Life Percentage	100%
Tire Condition Notes	New
Wheel Rims & Nuts	Ok
Front Left	-
Tire Brand & Size Details	VIZZONI 26.5-25
Tire Remaining Life Percentage	100%
Tire Condition Notes	New
Wheel Rims & Nuts	Ok
Rear Right	-
Tire Brand & Size Details	BKT 26.5-25
Tire Remaining Life Percentage	80%
Tire Condition Notes	Ok
Wheel Rims & Nuts	Ok
Rear Left	-
Tire Brand & Size Details	BKT 26.5-25

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Tire Remaining Life Percentage	80%
Tire Condition Notes	Ok
Wheel Rims & Nuts	Ok

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

