

PLANT & EQUIPMENT

Inspection report – 2009 Terex T560-1

Serial No: 52522 | Location: Dubai, United Arab Emirates | SKU: 1196

Key Features & Condition

CE Labeling	N/A
Automatic Shift	YES
Semi-Automatic	N/A
Tachograph	N/A
Auto Lube	N/A
A/C	N/A
Extended Fuel tank	YES
Retarder	N/A
2 Axle Steering	YES
Front axle lifter	Not functional

Truck Cab

Driver Seat	Ok
Switches, Levers	Ok
Gauges, Warn Lights	Ok, glass need polish
Aircon / Heater	Not functional
Cab Doors	Ok
Windows, Mirrors	Ok
Wipers, Washers	Not functional
Interior, Covers	Ok

Crane operator cab

Driver Seat	Ok
Switches, Levers	Ok, no steering switches
Gauges, Warn Lights	Ok, gauges glass need polish
Aircon / Heater	N/A
Cab Doors	Ok
Windows	Ok
Interior, Covers	Not functional

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Wipers

Ok

Engine

Injection Type

Electronic

Engine Model

Detroit diesel 60 series

Leaks, Seals

Minor gasket leaks

Oil Condition

Ok

Exhaust/Muffler

Ok

Cooling System

Ok

Smoke, Fume

Normal

Blow By

Normal

Belts, Pulleys

Ok

Coolant Condition

Normal water

Visual inspection exterior

Chassis, Frames

Ok

Sheet Metal, Covers

Ok

Steps, Grab Irons

Ok

Paintwork

Ok, repainted

Cooler Grill

Ok

Bumpers

Ok

Lights

Ok

Batteries

Need replace

Main Hook

Ok

Auxiliary Hook

Ok

Power Train

Axels/Differentials

Functional

Stabilizers, Beams

Functional, front left beam need service

Rubber Suspension

Functional

Brake Pads/Disks

Functional

Compressor

Ok

Transfer Gear

Functional

Universal Joints

Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Transmission

Automatic

Clutch

N/A

Hydraulics / Steering

Hoses & Lines

Ok

Hydraulic Pump

Functional

PTO

Functional

Steering Cylinders

Functional

Steering Linkage

Ok

Lift Limitations

Not functional

Outriggers

Top pads minor cracks

HoOk

Ok

Boom Cylinder

Minor rust, minor leaks

Crane Condition / Limited Test

Drive Forward & Back

Functional

Controls, Levers

Functional

Boom Conditions

Ok

Telescopic Segments

Ok

Hydraulic Cylinders

Functional drive

Swing Bearing / Drive

Functional need drive & brake service

Hose Lines

Ok

Lift Limitations

Not functional

Main Hook

Ok

Auxiliary Hook

Ok

Outriggers

Functional, front left beam need service

Tires Condition %

Right

-

Axle 1

60%

Axle 2

40%

Axle 3 outside

60%

Axle 3 inside

60%

Axle 4 outside

60%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Axle 4 inside	60%
Left	-
Axle 1	50%
Axle 2	50%
Axle 3 outside	60%
Axle 3 inside	40%
Axle 4 outside	60%
Axle 4 inside	60%

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

