

## Inspection report – 2010 Caterpillar 140K

Serial No: CAT0140KJSZL00241 | Hours: 526 | Location: Dubai, United Arab Emirates | SKU: 987

---

### Key Features & Condition

Safety Certification Label	N/A
Supplemental Steering System	N/A
Ground Loosening Tool (Scarifier)	N/A
Emission Compliance Label	N/A
Snowplow Attachment	N/A
Equipment Parts Manual	N/A
Ripper Control Valve	N/A
All-Wheel Drive System	N/A
Ground Tearing Tool (Ripper)	N/A
Operator's Manual	N/A
Front Plow Blade	N/A

### Operator Cabin Details

Seat	Ok
Control Levers	Ok
Dashboard Gauges & Lights	Need minor service
Warning alarms Lights, Message	Service light blinking
Air conditioning	Ok
Cab Floor Covering	Not original
Windows and Mirrors	Ok
Cab Doors	Ok, left door lock need repair
Windshield Wipers and Washer	Only front wiper
Access Steps and Handles	Ok
Cab Structure, Guard	Ok, no guard
Electrical System	Need minor service

### Engine & Performance

Fuel Injection Type	Electronic
Engine Model Details	C7

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Fluid Leaks and Seals	Ok, minor
Engine Oil Check	Ok
Exhaust System and Muffler	Ok
Exhaust Smoke	Minor
Engine Cooling System	Ok
Engine Blow-by Check	Minor
Belts and Air/Oil Filters	Ok
Coolant Check	Ok

---

## Exterior Condition & Visual Inspection

Main Frame Structure	Ok
Cabin Body Condition	Ok
Y-Frame Structure	Ok
Y-Frame Pivot Joint	Ok
Circle Frame & Brackets	Ok, Minor crack and welding
Circle Support Brackets	Ok
Circle Gear	Ok
Blade Slide Wear Strips	Ok
Steering Linkage	Ok
Underbody Protection Plates	N/A
Exterior Paint Condition	Ok
Lights	N/A
Engine Access Doors	Ok
Sheet Metal	Ok
Tandem Axles	Ok
Blade Tilt Frame (saddle)	Ok
Circle Wear Strips	Ok
Circle Gear Box	Ok
Articulating Centre Pins Wear	Ok
Front Axle Oscillating Pin Wear	Loose
Wheel Tilt Linkage	N/A
Main Blade	Ok
Ground Ripper	N/A
Batteries	Ok

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Hydraulic System

Hydraulic Leaks	Ok
Rotating Gear Drive	Ok
Hydraulic Control Valves	Ok
Hydraulic Pumps	Ok
Saddle Positioning Cylinder	N/A
Steering Hydraulic Cylinders	Ok, left minor leaks
Blade Cylinders/ Angle, lift, side	Ok
Ripper Hydraulic Cylinders	N/A
Articulation Hydraulic Cylinders	Functional, need minor service
Tires lean cylinder	N/A

## Limited Functional Testing & Operation

Gear Shifting Test	Functional
Tandem Axle Noise Check	Ok
Brake System Test	Functional
Steering Function Test	Functional
Tires Lean Function Test	Functional, need service
Electrical System Check	Need minor service
Blade Attachment Pins	Minor loose
Blade Side Movement Shifting	Functional
Rotating Circle Movement Check	Functional on one side (need service)
Front Blade Function Test	N/A
Ripper & Scarifier Function Test	N/A
Steering Tires Angle Adjustment	N/A
Clutch Operation Test	Functional , Need minor service

## Tires Inspection

Position	Remaining Life (%) / Tire Brand & Size Details
Front Right Tire	80% JKTYRE 1400-24
Front Left Tire	80% JKTYRE 1400-24
Center Right Tire	80% NARF 1200-24
Center Left Tire	80% NARF 1200-24
Rear Right Tire	80% NARF 1200-24

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Rear Left Tire

80% NARF 1200-24

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

