

Inspection report – 2010 Caterpillar 140K

Serial No: CAT0140KJSZL00241 | Hours: 526 | Location: Dubai, United Arab Emirates | SKU: 901

Key Features & Condition

|                                   |     |
|-----------------------------------|-----|
| Safety Certification Label        | N/A |
| Supplemental Steering System      | N/A |
| Ground Loosening Tool (Scarifier) | N/A |
| Emission Compliance Label         | N/A |
| Snowplow Attachment               | N/A |
| Equipment Parts Manual            | N/A |
| Ripper Control Valve              | N/A |
| All-Wheel Drive System            | N/A |
| Ground Tearing Tool (Ripper)      | N/A |
| Operator’s Manual                 | N/A |
| Front Plow Blade                  | N/A |

Operator Cabin Details

|                                |                                |
|--------------------------------|--------------------------------|
| Seat                           | Ok                             |
| Control Levers                 | Ok                             |
| Dashboard Gauges & Lights      | Need minor service             |
| Warning alarms Lights, Message | Service light blinking         |
| Air conditioning               | Ok                             |
| Cab Floor Covering             | Not orginal                    |
| Windows and Mirrors            | Ok                             |
| Cab Doors                      | Ok, left door lock need repair |
| Windshield Wipers and Washer   | Only front wiper               |
| Access Steps and Handles       | Ok                             |
| Cab Structure, Guard           | Ok, no guard                   |
| Electrical System              | Need minor service             |

Engine & Performance

|                      |            |
|----------------------|------------|
| Fuel Injection Type  | Electronic |
| Engine Model Details | C7         |



|                            |           |
|----------------------------|-----------|
| Fluid Leaks and Seals      | Ok, minor |
| Engine Oil Check           | Ok        |
| Exhaust System and Muffler | Ok        |
| Exhaust Smoke              | Minor     |
| Engine Cooling System      | Ok        |
| Engine Blow-by Check       | Minor     |
| Belts and Air/Oil Filters  | Ok        |
| Coolant Check              | Ok        |

---

## Exterior Condition & Visual Inspection

|                                 |                             |
|---------------------------------|-----------------------------|
| Main Frame Structure            | Ok                          |
| Cabin Body Condition            | Ok                          |
| Y-Frame Structure               | Ok                          |
| Y-Frame Pivot Joint             | Ok                          |
| Circle Frame & Brackets         | Ok, Minor crack and welding |
| Circle Support Brackets         | Ok                          |
| Circle Gear                     | Ok                          |
| Blade Slide Wear Strips         | Ok                          |
| Steering Linkage                | Ok                          |
| Underbody Protection Plates     | N/A                         |
| Exterior Paint Condition        | Ok                          |
| Lights                          | N/A                         |
| Engine Access Doors             | Ok                          |
| Sheet Metal                     | Ok                          |
| Tandem Axles                    | Ok                          |
| Blade Tilt Frame (saddle)       | Ok                          |
| Circle Wear Strips              | Ok                          |
| Circle Gear Box                 | Ok                          |
| Articulating Centre Pins Wear   | Ok                          |
| Front Axle Oscillating Pin Wear | Loose                       |
| Wheel Tilt Linkage              | N/A                         |
| Main Blade                      | Ok                          |
| Ground Ripper                   | N/A                         |
| Batteries                       | Ok                          |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



---

## Hydraulic System

|                                    |                                |
|------------------------------------|--------------------------------|
| Hydraulic Leaks                    | Ok                             |
| Rotating Gear Drive                | Ok                             |
| Hydraulic Control Valves           | Ok                             |
| Hydraulic Pumps                    | Ok                             |
| Saddle Positioning Cylinder        | N/A                            |
| Steering Hydraulic Cylinders       | Ok, left minor leaks           |
| Blade Cylinders/ Angle, lift, side | Ok                             |
| Ripper Hydraulic Cylinders         | N/A                            |
| Articulation Hydraulic Cylinders   | Functional, need minor service |
| Tires lean cylinder                | N/A                            |

---

## Limited Functional Testing & Operation

|                                  |                                       |
|----------------------------------|---------------------------------------|
| Gear Shifting Test               | Functional                            |
| Tandem Axle Noise Check          | Ok                                    |
| Brake System Test                | Functional                            |
| Steering Function Test           | Functional                            |
| Tires Lean Function Test         | Functional, need service              |
| Electrical System Check          | Need minor service                    |
| Blade Attachment Pins            | Minor loose                           |
| Blade Side Movement Shifting     | Functional                            |
| Rotating Circle Movement Check   | Functional on one side (need service) |
| Front Blade Function Test        | N/A                                   |
| Ripper & Scarifier Function Test | N/A                                   |
| Steering Tires Angle Adjustment  | N/A                                   |
| Clutch Operation Test            | Functional , Need minor service       |

---

## Tires Inspection

|                   |                                                |
|-------------------|------------------------------------------------|
| Position          | Remaining Life (%) / Tire Brand & Size Details |
| Front Right Tire  | 80% JKTYRE 1400-24                             |
| Front Left Tire   | 80% JKTYRE 1400-24                             |
| Center Right Tire | 80% NARF 1200-24                               |
| Center Left Tire  | 80% NARF 1200-24                               |
| Rear Right Tire   | 80% NARF 1200-24                               |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Rear Left Tire

80% NARF 1200-24

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

**PANDE Auctions LLC**

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

