

Inspection report – 2011 Komatsu PC400LC

Serial No: KMTPC196E53J30295 | Hours: 21463 | Location: Dubai, United Arab Emirates | SKU: 902

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	N/A
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A
Rear Camera	N/A
E-Cataloge	N/A
Radio	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & Covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Need service (Dark)
Warning Alarms Message	E11ca123, coolant level sensor, clogged air cleaner
Washer, Wipers	Not functional
Air Conditioning & Heating System	Ok, weak cooling
Cab Floor Covering	Ok
Cab Structure	Ok
Electrical System	Need minor service

Engine & Performance

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Fuel Injection System	Electronic
Engine Model	Komatsu SAA6D125E-5
Engine Cooling System	Ok
Engine Oil Check	Ok
Coolant	Ok, normal water
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok, filters need change
Smoke Check	Normal
Blowby	Normal
Leaks & Seals	Minor oil leak

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok, 4 missing covers
Engine Hood	Ok, rear need minor welding
Side Access Doors	Ok, 1 need lock
Steps and Handrails	Ok
Boom Condition	Ok
Bumper & Catwalk Condition	Ok, bumper minor dent
Arm Condition	Ok, Has a minor crack
Lights	Ok, 2- lights need bulbs
Battery Check	Need change
Cabin Compartments	Ok
Exterior Paint Condition	Ok

Hydraulic System

Hydraulic Leaks	Ok
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok

Performance analysis

Boom Pins Condition	Ok
---------------------	----

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Excavator self- Drift Test	Ok
Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Ok
Slewing Ring Bearing Movement Check	Ok
Swing Drive and Brake Test	Ok
Drive force Test	Ok

Attachments

Attachments model	Bucket
Size	W1100, H1300, D1200 mm
Status	Ok
Coupler status	Ok
Second Attachments model	N/A
Size	N/A
Status	N/A

Undercarriage

Bushings	20%
Track Shoes	30%
Idlers	60%
Shoe Width in mm:	800 mm
Track Pitch in mm:	80
Carrier Rollers	30%
Track Rollers	20%
Track Links	25%
Sprocket Segments	60%

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

