

## Inspection report – 2011 Massey Ferguson 6480

Serial No: B160017 | Hours: 4068 | Location: Dubai, United Arab Emirates | SKU: 911

---

### Key Features & Condition

Safety Certification Label	N/A
Environmental Protection Agency	N/A
A/C	N/A
PTO	Yes
4WED	Yes
All Wheel Steer	N/A
3-Point Linkage	Yes
Drawbar	Yes
Emission Compliance Label	N/A
Horn Function	N/A
Closed Cabin	Yes
CE Specification	Yes
Shift Speed Controller	Yes
Front Axle Suspension	N/A
Cabin Suspension	Yes
Engine Speed Memory Control	Yes

### Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok, left door glass broken and lock need repair
Controls, Levers	Ok
Windows and Mirrors	Ok, front left mirror missing
Dashboard Screen, Gauges	Ok, monitor not functional
Warning alarms message	Error E9151, E9023, air flow sensor, oil pressur, oil temperture
Washer, Wipers	Ok, rear not functional
Air Condition & Heating System	Not functional
Cab Floor Covering	Ok
Cab Structure	Ok

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Electrical System

Need service

---

## Engine & Performance

Fuel Injection Type

Electronic

Engine Model

SisuDiesel / 6 cyl.Turbo/intercooled

Engine Cooling System

Ok

Engine Oil Check

Ok

Blowby

Normal

Exhaust System & Muffler

Ok

Belts & Air/Oil Filters

Ok, filters need change

Smoke

Normal

Coolant

Normal water

Fluid Leaks

Minor oil leak from turbo gasket, minor diesel leak from first injector feed pipe

---

## Exterior Condition & Visual Inspection

Chassis

Ok

Engine Hood

Ok

Steering Linkage

Ok

Access Steps and Handrails

Ok

Exterior Paint Condition

Ok

Sheet Metal

N/A

Wheel Fenders

Ok, front right missing

Lights Check

Not functional, 1 missing

Battery Check

Ok

Rims, Wheel Nuts

Ok

---

## Power Train Inspection

Axles and Differentials

Ok

Transmission Leak

Ok

Power Train force

Ok

Transmission Noise Check

Ok

Universal Joint Condition

Ok

Transfer Gear Type

Semi-Auto 4 gear

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



## Hydraulic System

Hydraulic Leaks	Ok
Remote Hydraulic Controls	Available, not tested
Steering Hydraulic Jacks	Ok
Hydraulic Pumps and Valves	Ok
Cylinder(s)	N/A

## Limited Functional Testing & Operation

Steering Function Test	Ok
Transmission Operation Test	Ok
Cylinder Pins and Bushings	N/A
Braking System Test	Ok

## Tires Estimated Remaining Life %

Front Right	-
Tire Brand & Size Details	ASCENSO 16,9-28
Tire Remaining Life Percentage	100%
Tire Condition Notes	Tubeless / new
Front Left	-
Tire Brand & Size Details	ASCENSO 16,9-28
Tire Remaining Life Percentage	100%
Tire Condition Notes	Tubeless / new
Rear Right	-
Tire Brand & Size Details	ASCENSO 600/ 65R38
Tire Remaining Life Percentage	100%
Tire Condition Notes	Tubeless / new
Rear Left	-
Tire Brand & Size Details	ASCENSO 600/ 65R38
Tire Remaining Life Percentage	100%
Tire Condition Notes	Tubeless / new

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

