

Inspection report – 2012 Atlas Copco F9 LF20

Serial No: 12A15428992008383 | Hours: 15123 | Location: Dubai, United Arab Emirates | SKU: 952

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Automatic Lubrication System	N/A
Diesel Particulate Filter	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade	N/A
Horn	N/A
Rear Camera	N/A
E-Cataloge	N/A
Radio	N/A
CE Mark	Yes
Emergency Stop	Need replace

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok, only left mirror
Dashboard Screen, Gauges	Ok, gauges need service
Warning alarms message	Ok
Washer, Wipers	Not functional
Air Conditioning & Heating System	Not cooling
Cab Floor Covering	Ok
Cab Structure, Guard	Ok
Electrical System	Need service

Engine & Performance

Fuel Injection System	Electronic
Engine Model	C9

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Engine Cooling System	Ok
Engine Oil Check	Ok
Coolant	Normal water
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke Check	Minor
Blowby	Normal
Leaks & Seals	Ok

Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok, front right lock need service
Steps and Handrails	Ok
Boom Condition	Ok
Vices	Ok
Lights	Not functional
Battery Check	Need change
Cabin Compartments	Ok
Exterior Paint Condition	Ok
Stake Down System	N/A
Kelly Drive Gear Box	N/A
Thrust Chain / Sprockets	Not functional
Drill Rod Loading System	N/A
Drill Rod Racks	Avilable
Dust Collection System	Not functional du to air copressur
Mast Condition	Rusty

Hydraulic System

Hydraulic Leaks	Multi leaks
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Stabilizer Cylinders	N/A

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Mast Angle Cylinders	Ok, minor oil leak
Drifter Cylinder	Ok, minor oil leak

Performance analysis

Boom Pins Condition	Ok
Hydraulic Pump Noise Check	Ok
Drive force Test	Ok
Stake Down System	N/A
Vices	Functional
Drill Rod Loading System	N/A
Air Compressor	Not functional
Dust Collection System	Not functional

Undercarriage

Bushings	60%
Track Shoes	70%
Idlers	70%
Shoe Width In Mm:	330
Track Pitch In Mm:	50
Carrier Rollers	70%
Track Rollers	70%
Track Links	70%
Sprocket Segments	60%

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

