

## Inspection report – 2013 Caterpillar 226B3

Serial No: CAT0226BESNA00162 | Hours: 22873 | Location: Dubai, United Arab Emirates | SKU: 1021

---

### Key Features & Condition

|                            |     |
|----------------------------|-----|
| Safety Certification Label | N/A |
| Operator's Manual          | N/A |
| Equipment Parts Manual     | N/A |
| Air Conditioning System    | N/A |
| Emission Compliance Label  | N/A |
| Closed Cabin               | N/A |
| Horn Function              | N/A |

---

### Operator Cabin Details

|                                   |                                                                                             |
|-----------------------------------|---------------------------------------------------------------------------------------------|
| Seat and Arm Support              | Ok, need upholstery                                                                         |
| Cab Doors & covers                | Ok                                                                                          |
| Control Levers, Control Stick     | Functional, minor leak                                                                      |
| Windows and Mirrors               | Only rear window, right mirror, and center mirror cracked, left mirror handle not original. |
| Gauges                            | Fuel gauge need replace                                                                     |
| Warning alarms message            | N/A                                                                                         |
| Washer, Wipers                    | N/A                                                                                         |
| Air Conditioning & Heating System | N/A                                                                                         |
| Cab Floor Covering                | Ok                                                                                          |
| Cab Structure, Guard              | Ok                                                                                          |
| Electrical System                 | Ok                                                                                          |
| Start key                         | Ok                                                                                          |
| Main Safety Switch                | Ok                                                                                          |
| Engine rpm Throttle Lever         | Not functional                                                                              |

---

### Engine & Performance

|                       |                           |
|-----------------------|---------------------------|
| Fuel Injection Type   | Mechanical                |
| Engine Model          | C2.2 Serial nom: CYS21623 |
| Engine Cooling System | Ok                        |

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                          |                   |
|--------------------------|-------------------|
| Engine Oil Check         | Ok                |
| Blowby                   | Minor             |
| Exhaust System & Muffler | Ok                |
| Belts & Air/Oil Filters  | Ok                |
| Smoke                    | Normal            |
| Coolant                  | Normal water      |
| Leaks& seals             | Minor Gasket leak |

---

## Exterior Condition & Visual Inspection

|                            |             |
|----------------------------|-------------|
| Main Frame and Lift Arm    | Ok          |
| Protective Covers & Sheets | Ok          |
| Engine Door                | Ok, no Lock |
| Lights                     | Ok          |
| Battery Check              | Ok          |
| Exterior Paint Condition   | Repainted   |

---

## Hydraulic System

|                                          |             |
|------------------------------------------|-------------|
| Hydraulic Leaks                          | Minor leaks |
| Lift and Tilt Hydraulic Jack             | Ok          |
| Steering Hydraulic Orbital (drive motor) | Ok          |
| Hydraulic Pumps and Valves               | Functional  |

---

## Limited Functional Testing & Operation

|                         |             |
|-------------------------|-------------|
| Drive Function Test     | Functional  |
| Skid steer Stall Test   | Functional  |
| Brake System Test       | Functional  |
| Attachment Pins         | Minor Loose |
| Final Drive Motors Test | Functional  |
| Park Break              | Functional  |

---

## Attachments

|                   |                      |
|-------------------|----------------------|
| Attachments model | Bucket               |
| Size              | W1530, H700, D400 mm |

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



|                        |              |
|------------------------|--------------|
| Bottom condition       | Ok           |
| Edge & teeth condition | Ok, no teeth |
| Bucket side condition  | Ok           |
| Coupler status         | Ok           |

---

## Tires Estimated Remaining Life %

|                   |                   |
|-------------------|-------------------|
| Front Right       | 40%               |
| Front Left        | 40%               |
| Rear Right        | 40%               |
| Rear Left         | 40%               |
| Size              | 10-16.5           |
| Type              | Tube less         |
| wheel Rims & Nuts | Ok, 1 nut missing |

---

## Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

