

PLANT & EQUIPMENT

Inspection report – 2015 Caterpillar 966H

Serial No: CAT0966HJBJ601493 | Hours: 27444 | Location: Dubai, United Arab Emirates | SKU: 1174

Key Features & Condition

Safety Certification Label	N/A
Automatic Lubrication System	N/A
Auxiliary Hydraulic Valve	N/A
Equipment Parts Manual	N/A
Air Conditioning System	Ok
Hydrostatic Drive System (Hydrostat)	N/A
Supplemental Steering System	Ok
Operator's Manual	N/A
Emission Compliance Label	N/A
Quick Attachment Coupler	N/A
Load Weighing System	N/A
Horn Function	Ok

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	96-3, 351-13, 274-3
Washer, Wipers	Ok, rear wiper missing
Air Conditioning & Heating System	Ok
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Need minor service

Engine & Performance

Fuel Injection Type	Electronic
---------------------	------------



PLANT & EQUIPMENT

Engine Model	C11
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok
Smoke	Normal
Coolant	Normal water
Fluid Leaks	Minor leaks

Exterior Condition & Visual Inspection

Main Frame and Lift Arm	Ok
Engine Hood	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok
Counterweight Condition	Ok
Wheel Fenders	Ok
Lights Check	Ok
Battery Check	Ok
Covers	Engine left cover missing

Power Train Inspection

Axles and Differentials	Ok
Transmission Gearbox	Minor oil leak
Power Train force	Ok
Transmission Noise Check	Ok
Universal Joint Condition	Ok
Transfer Gear Type	Semi- auto

Hydraulic System

Hydraulic Leaks	OK, minor leaks
Lift and Tilt Hydraulic Jack	Ok, minor leak
Steering Hydraulic Jacks	Ok, minor leak
Hydraulic Pumps and Valves	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Limited Functional Testing & Operation

Steering Function Test	Ok
Transmission Operation Test	OK, 2nd front gear not functional
Loader Stall Test	Ok
Brake System Test	Ok
Articulation Movement Check	Ok
Loader Attachment Pins	Ok, bucket pins minor loose

Attachments

Bucket Width and Capacity	W3200, H1500, D1000 mm
Bucket Bottom Condition	Minor Damaged
Bucket Edge & Teeth Condition	Ok, no teeth
Bucket Side Condition	Ok
Attachment Coupler	Ok

Tires Inspection

Front Right	-
Tire Brand & Size Details	MAXAM, 26.5R25
Tire Remaining Life Percentage	70%
Tire Condition Notes	Good, Tubeless
Wheel Rims & Nuts	Ok
Front Left	-
Tire Brand & Size Details	ITR, 26.5R25
Tire Remaining Life Percentage	50%
Tire Condition Notes	Good, Tubeless
Wheel Rims & Nuts	Ok
Rear Right	-
Tire Brand & Size Details	MAXAM, 26.5R25
Tire Remaining Life Percentage	70%
Tire Condition Notes	Good, Tubeless
Wheel Rims & Nuts	Ok
Rear Left	-
Tire Brand & Size Details	Advance 26.5R25
Tire Remaining Life Percentage	70%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Tire Condition Notes

Good, Tubeless

Wheel Rims & Nuts

Ok

Disclaimer

All equipment and assets are offered for sale on an "As Is, Where Is" basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

