

PLANT & EQUIPMENT

Inspection report – 2015 Caterpillar D6R XL

Serial No: CAT00D6RAJEN00313 | Hours: 15874 | Location: Dubai, United Arab Emirates | SKU: 1197

Key Features & Condition

Safety Certification Label	N/A
Ground Ripper	N/A
Ripper Control Valve	N/A
Low Ground Pressure Tracks	N/A
Operator's Manual	N/A
Emission Compliance Label	N/A
Grade Control System	N/A
Equipment Parts Manual	N/A
CAT System One	N/A
Horn	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok
Windows and Mirrors	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok
Air Conditioning & Heating System	Not Functional
Cab Floor Covering	N/A
Cab Structure, Gard	N/A
Electrical System	Ok, need minor service (Engine RPM)

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	C9
Engine Cooling System	Ok



PLANT & EQUIPMENT

Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Ok, filters need change
Smoke	Minor
Coolant	Ok, normal water
Fluid Leaks	Ok, minor gasket leak
Fuel System	Need minor service

Exterior Condition & Visual Inspection

Push Frame & Trunnions	Ok
Doors, Covers, and Grilles	Ok
Access Steps & Handrails	Ok
Exterior Paint Condition	Ok
Blade Trunnions & Bushings	Ok
Underbody Protection Plates	Ok
Final Drive Condition	Functional
Fuel Tank, Roof, & Hood Condition	Ok
Lights and Battery Check	Need battery and terminals, rear lights missing
Push Arm Pivot Shaft	Ok
Tilt Linkage Pins & Bushings	Ok

Hydraulic System

Hydraulic Leaks	Ok
Lift Hydraulic Jacks	Ok
Ripper Lift Hydraulic Jacks	N/A
Tilt Hydraulic Jack	Ok
Angle Hydraulic Jack	N/A
Ripper Angle Hydraulic Jacks	N/A

Limited Functional Testing & Operation

Push Frame Pins	Ok
Blade Pins	Ok
Ripper Pins	N/A

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Equalizer Bar Condition	Ok
Bulldozer Stall Test	Ok
Steering Function Test	Ok
Blade Tilt and Lift Test	Ok
Undercarriage Pivot Pins	Ok
Transmission Test	Functional
Brake System Test	Ok
Torque Converter Test	Functional

Blade Inspection

Blade Base Condition	Ok
Spill Rack Condition	Ok
Blade Front Condition	Ok
Blade Edge Condition	Ok

Undercarriage Inspection

Right Side Undercarriage Wear	-
Undercarriage Bushings	80%
Undercarriage Shoes	70%
Front Idler Condition	90%
Rear Idler Condition	90%
Carrier Roller Condition	90%
Track Links Condition	90%
Sprocket Condition	90%
Roller Condition	90%
Track Canon Condition	70%
Left Side Undercarriage Wear	-
Undercarriage Bushings	80%
Undercarriage Shoes	70%
Front Idler Condition	90%
Rear Idler Condition	90%
Carrier Roller Condition	90%
Track Links Condition	90%
Sprocket Condition	90%

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT

Roller Condition	90%
Track Canon Condition	70%
Track Width Measurement	W560, L230 mm

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

