

## Inspection report – 2016 Caterpillar TH417C GC

Serial No: YC5A1251JNMM00222 | Hours: 22259 | Location: Dubai, United Arab Emirates | SKU: 776

### **Key Features & Condition**

Safety Certification Label N/A Axle Based 4WD N/A **Electric Powered** N/A **Equipment Parts Manual** N/A N/A **Electric Operating System** N/A Horn Function Travel Alarm N/A N/A Operator's Manual **Emission Compliance Label** N/A **Diesel Powered** Yes

Distinct Steering Modes Yes (3 types)

#### **Operator Cabin Details**

Seat and Arm Support Ok, need upholstery

Control levers, Control swithes Ok

Dashboard Screen, Gauges Screen need change

Warning alarms message Code 437

Electrical System Ok, 1 sensor is broken
Windows/ mirrors/ Wipers Ok,door window is broken

Floor Mats Ok, not orginal Air Conditioning & Heating System Not cooling

#### **Engine**

Model TCD 3.6 L4\*
Injection Type Electronic

Leaks Ok
Oil Condition Ok

Exhaust Smoke Normal

#### **PANDE Auctions LLC**

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



# PLANT & EQUIPMENT AUCTIONS

Cooling System Ok

Coolant Ok, normal water

Sound Ok

Blow By Normal

Belts Ok Power Ok

### **Exterior Condition & Visual Inspection**

Chassis Ok Sheet Metal Ok Side Doors Ok **Boom Condition** Ok Boom Linkage / Guides Ok **Paintwork** Ok Cooler Grill Ok Frame Condition Ok Outriggers Ok **Batteries** Ok

Lights Ok, 1 broken, need 3 bulbs

Fenders Ok, minor cracks

#### **Hydraulic System**

Hoses,Lines,Swivel Ok
Pump And Valve Bloc Ok

Steering Cylinder Ok, front left minor oil leak

Boom Lift Cylinder(s)

Telescopic Boom Cylinders

Ok
Carriage Tilt Cylinder

N/A
Frame Leveling Cylinders

Ok
Stabilizer Cylinders

Ok
Leaks

Ok

#### **Drivetrain**

Transmission Ok

#### **PANDE Auctions LLC**

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



# PLANT & EQUIPMENT AUCTIONS

Transfar Gear type semi auto (single-lever joystick)

Transfer Case / Drop Box Ok
Front / Rear Axle Ok

#### **Limited Functional Testing & Operation**

**Drive Forward** Ok **Drive Reverse** Ok Steering Ok Platform Function Controls Ok **Boom Extension** Ok Fork angle movment Ok Wheel Bearing Ok **Brake System** Ok Lifting Ok

### Tires condition / Type / Size

Axle 1 Right 20% EUROGRIP 14.00-24 tubless

Axle 1 Left 30% OTANI 14.00-24 tubless

Axle 2 Right 30% OTANI 14.00-24 tubless

Axle 2 Left 30% ASCENSO 14.00-24 tubless

#### **Attachments**

Coupler Condition Ok

Tool 1 Fork

Size L1150,W100 mm

Condition Ok

Tool 2 Bucket

Size W2350, H800, D500 mm

Condition Ok

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.



Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com

