

Inspection report – 2018 Hyundai R220-9S

Serial No: HHKHN60H22L90262T | Location: Dubai, United Arab Emirates | SKU: 840

Key Features & Condition

| | |
|-------------------------------------|-----|
| Safety Certification Label | N/A |
| Boom Hydraulic Check Valve | N/A |
| Adjustable Boom System | N/A |
| Automatic Lubrication System | N/A |
| Arm Hydraulic Check Valve | N/A |
| Diesel Particulate Filter | N/A |
| Hydraulic Hammer Lines | Yes |
| Grapple and Shear Hydraulic Lines | N/A |
| Diesel Exhaust Fluid System AddBlue | N/A |
| Stabilizer Blade Condition | N/A |
| Horn | N/A |
| Quick Coupler | Yes |

Operator Cabin Details

| | |
|-----------------------------------|--|
| Seat and Arm Support | Ok |
| Cab Doors & covers | Ok, lock need repair |
| Control Levers, Control Stick | Ok |
| Windows and Mirrors | The front window is cracked, mirrors are missing |
| Dashboard Screen, Gauges | Ok |
| Warning alarms message | Ok |
| Washer, Wipers | Missing |
| Air Conditioning & Heating System | Not functional |
| Cab Floor Covering | Ok |
| Cab Structure, Gard | Ok |
| Electrical System | Ok |

Engine & Performance

| | |
|-----------------------|------------|
| Fuel Injection System | Mechanical |
|-----------------------|------------|

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|--------------------------|----------------|
| Engine Model | CUMMINS B5.9-C |
| Engine Cooling System | Ok |
| Engine Oil Check | Ok |
| Cooling System | Ok |
| Coolant | Ok |
| Exhaust System & Muffler | Ok |
| Belts & Air/Oil Filters | Ok |
| Smoke Check | Normal |
| Blowby | Normal |
| Leaks & Seals | Ok |

Exterior Condition & Visual Inspection

| | |
|-----------------------------|--------------------------------------|
| Main Frame & Track Frame | Ok, the main frame has minor dents |
| Protective Covers & Sheets | Ok, minor dents |
| Engine Hood | Ok |
| Side Access Doors | Ok |
| Steps and Handrails | Ok |
| Boom Condition | Ok |
| Bumpers & Catwalk Condition | Ok |
| Arm Condition | Ok, minor welding on bucket pin bush |
| Lights | 1 functional light |
| Battery Check | Ok |
| Cabin Compartments | Ok |
| Exterior Paint Condition | Ok, rusty |

Hydraulic System

| | |
|------------------------------|--------------------|
| Hydraulic Leaks | Ok, minor |
| Boom Hydraulic Jack | Ok |
| Hydraulic Pump & Valve Block | Ok |
| Bucket Hydraulic Jack | Ok |
| Arm Hydraulic Jack | Ok |
| Quick Coupler Jack | Ok, minor oil leak |

Performance analysis

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



| | |
|-------------------------------------|----|
| Boom Pins Condition | Ok |
| Excavator self- Drift Test | Ok |
| Arm Pins Condition | Ok |
| Hydraulic Pump Noise Check | Ok |
| Bucket Pins Condition | Ok |
| Slewing Ring Bearing Movement Check | Ok |
| Swing Drive and Brake Test | Ok |
| Drive force Test | Ok |

Attachments

| | |
|--------------------------|---------------------------------|
| Attachments Model | Bucket |
| Size | W1150, H1200, D800 mm |
| Status | Ok, the bottom is minor damaged |
| Coupler Status | Ok |
| Second Attachments Model | N/A |
| Size | N/A |
| Status | N/A |

Undercarriage

| | |
|--------------------|-----|
| Bushings | 40% |
| Track Shoes | 40% |
| Idlers | 35% |
| Shoe Width In Mm: | 600 |
| Track Pitch In Mm: | 70 |
| Carrier Rollers | 20% |
| Track Rollers | 30% |
| Track Links | 40% |
| Sprocket Segments | 60% |

Notes:

The excavator is in working condition, and all its major parts are intact and functioning as intended. The model year is not verified. There is no chassis punching serial number.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT | AUCTIONS

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

