

Inspection report – 2018 JCB 380LC

Serial No: PUNJD38CCJ2500802 | Hours: 17170 | Location: Dubai, United Arab Emirates | SKU: 1036

Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	N/A
Adjustable Boom System	N/A
Automatic Lubrication System	Yes
Arm Hydraulic Check Valve	N/A
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	N/A
Rear Camera	N/A
E-Cataloge	N/A
Radio	N/A

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok, front down glass has crack
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Washer, Wipers	Ok, not functional
Air Conditioning & Heating System	Extenal, ok
Cab Floor Covering	N/A
Cab Structure, Guard	Ok
Electrical System	Need service

Engine & Performance

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Fuel Injection System

Engine Model

Electronic, need service

JCB DIESELMAX 672 TCAE Electronic Engine.

Engine Cooling System

Ok

Engine Oil Check

Ok

Coolant

Ok, normal water

Exhaust System & Muffler

Ok

Belts & Air/Oil Filters

Ok

Smoke Check

Normal

Blowby

Normal

Leaks & Seals

Ok

Exterior Condition & Visual Inspection

Main Frame & Track Frame

Ok, minor welding on boom lift jack base

Protective Covers & Sheets

Ok

Engine Hood

Ok, lift support is missing

Side Access Doors

Ok

Steps and Handrails

Ok

Boom Condition

Ok

Bumpers & Catwalk Condition

Ok

Arm Condition

Minor crack, minor welding on bucket pin side

Lights

Ok, boom light is missing, need 2 bulbs

Battery Check

Ok

Cabin Compartments

Ok, fuse cover is missing

Exterior Paint Condition

Ok, some parts repainted

Hydraulic System

Hydraulic Leaks

Ok, minor

Boom Hydraulic Jack

Ok

Hydraulic Pump & Valve Block

Ok

Bucket Hydraulic Jack

Ok

Arm Hydraulic Jack

Ok

Performance analysis

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Boom Pins Condition	Ok, lift cylinder pin minor loose
Excavator self- Drift Test	Ok
Arm Pins Condition	Ok
Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Ok, minor loose
Slewing Ring Bearing Movement Check	Ok
Swing Drive and Brake Test	Ok, swing drive oil level is high
Drive force Test	Ok, right is little weaker

Attachments

Attachments model	Bucket
Size	W1550, H1300, D115 mm
Status	Ok
Coupler status	Ok
Second Attachments model	N/A
Size	N/A
Status	N/A

Undercarriage

bushings	50%
Track shoes	60%
idlers	R70%, L50%
shoe width in mm:	600
track pitch in mm:	80
carrier rollers	60%
Track rollers	60%
Track links	60%
Sprocket segments	70%

Disclaimer

All equipment and assets are offered for sale on an “As Is, Where Is” basis, with no warranties or guarantees expressed or implied.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Equipment information and inspection findings are based solely on visual observations made at the time of inspection. Plant & Equipment's inspectors, sellers, and consignors make no representations or warranties regarding the accuracy of the information provided, including the year of manufacture, operating hours, mileage, compliance, specifications, performance, or operating condition of the equipment.

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

