

Inspection report – 2018 Massey Ferguson MF7720

Serial No: VKKMX65EVJB108015 | Hours: 3208 | Location: Dubai, United Arab Emirates | SKU: 912

Key Features & Condition

Safety Certification Label	N/A
Environmental Protection Agency	N/A
A/C	N/A
PTO	Yes
4WED	Yes
All Wheel Steer	N/A
3-Point Linkage	Yes
Drawbar	Yes
Emission Compliance Label	N/A
Horn Function	N/A
Closed Cabin	Yes
CE Specification	Yes
Shift Speed Controller	Yes
Front Axle Suspension	Yes
Cabin Suspension	Yes
Engine Speed Memory Control	Yes
DEF	Yes
Spool valve	Yes
Cross control	Yes

Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Controls, Levers	Ok, main control lever is broken
Windows and Mirrors	Ok, left side glass broken, front left mirror missing
Dashboard Screen, Gauges	Ok
Warning alarms message	Service light is on
Washer, Wipers	Ok, rear not functional

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Air Condition & Heating System	Not Functional
Cab Floor Covering	Ok
Cab Structure	Ok
Electrical System	Need Service

Engine & Performance

Fuel Injection Type	Electronic
Engine Model	AGCO POWER 200 Hp (147 Kw)
Engine Cooling System	Ok
Engine Oil Check	Ok
Blowby	Normal
Exhaust System & Muffler	Ok
Belts & Air/Oil Filters	Need change
Smoke	Normal
Coolant	Ok
Fluid Leaks	Ok

Exterior Condition & Visual Inspection

Chassis	Ok
Engine Hood	Ok
Steering Linkage	Ok
Access Steps and Handrails	Ok
Exterior Paint Condition	Ok
Sheet Metal	Ok, engine side sheets missing
Wheel Fenders	Ok
Lights Check	Not Functional
Battery Check	Need change
Rims, Wheel Nuts	Ok

Power Train Inspection

Axles and Differentials	Ok
Transmission Leak	Ok
Power Train force	Ok
Transmission Noise Check	Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



Universal Joint Condition

Ok

Transfer Gear Type

Semi- Auto 4 gear

Hydraulic System

Hydraulic Leaks

Ok, minor

Remote Hydraulic Controls

Not tested

Steering Hydraulic Jacks

Not tested

Hydraulic Pumps and Valves

Not tested

Cylinder(s)

Not tested

Limited Functional Testing & Operation

Steering Function Test

Ok

Transmission Operation Test

Ok

Cylinder Pins and Bushings

Not tested

Braking System Test

Ok

Spool Valve Electronic/ Manual

Not tested

Tires Estimated Remaining Life %

Front Right

-

Tire Brand & Size Details

RUNGOD 18.4- 30

Tire Remaining Life Percentage

40%

Tire Condition Notes

Ok

Front Left

-

Tire Brand & Size Details

BKT 18.4- 30

Tire Remaining Life Percentage

90%

Tire Condition Notes

Ok

Rear Right

-

Tire Brand & Size Details

Galaxy 650/65R42

Tire Remaining Life Percentage

80%

Tire Condition Notes

Ok

Rear Left

-

Tire Brand & Size Details

Galaxy 650/65R42

Tire Remaining Life Percentage

90%

Tire Condition Notes

Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com



PLANT & EQUIPMENT | AUCTIONS

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +97148861125

www.PlantAndEquipment.com

