

Inspection report – 2018 Mercedes Benz Actros 1845

Serial No: WDB96340310246652 | Km: 558612 | Location: Dubai, United Arab Emirates | SKU: 764

Key Features & Condition

Rey i eatures & condition	
Safety Certification Label	Yes
Automatic Shift	Yes
Semi-Automatic	Yes
Cruise Control	Yes
Cabin Refrigerator	N/A
Add Blue	Yes
Hill Stand Aid Function	Yes
Horn Off-On	Yes
Tachograph	Yes
Auto Lube	N/A
A/C	Yes
Navigation	N/A
ABS	N/A
Driver Bed	Yes
Moving Off Aid	Yes
Lane Departure Warning System	Yes
Extended Fuel Tank	N/A
Retarder	Yes
Rear Axle Lifter	Yes
Radio	N/A
TRC	N/A
Camera Sensor	N/A
Differential Lock	Yes
Advanced Emergency Brake Assist	N/A

Truck Cabin Details

Seat And Arm Support Ok
Cab Doors & Covers Ok
Controls, Levers Ok

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



PLANT & EQUIPMENT AUCTIONS

Windows And Mirrors Ok
Dashboard Screen, Gauges Ok

Warning Alarms Message Ok, cabin lift sensor is on

Washer, Wipers Ok

Air Conditioning & Heating System Not cooling

Cab Floor Covering Ok Interior, Covers Ok Passenger Seat Ok

Radio Not functional

Engine & Performance

Fuel Injection Type Electronic

Engine Model M3B Eng. OM471,inline 6, 12.8 l, 330kW

(449hp),2200 Nm

Engine Cooling System Ok
Engine Oil Check Ok

Blowby Normal

Exhaust System & Muffler Ok, exhaust pipe elbo is welded

Belts & Air/Oil Filters Ok

Smoke Normal

Coolant Ok, mixed water- collant

Fluid Leaks Ok

Exterior Condition & Visual Inspection

Chassis, Frames Ok

Sheet Metal, Covers

Ok, batteries cover is missing

Steps, Grab Irons

Ok, left step minor cracked

Paintwork Ok Cooler Grill Ok

Bumpers Ok, side minor crack

Lights / Batteries Ok

Fenders Ok, front right is broken

Power Train

PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

www.PlantAndEquipment.com



PLANT & EQUIPMENT AUCTIONS

Axels/Differentials Ok
Stabilizers, Beams Ok
Rubber Sleeves Ok
Brake Pads/Disks Ok
Compressor Ok

Transfer Gear Ok, Auto

Universal Joints Ok
Transmission Ok
Clutch N/A

Truck Limited Functional Test

Transmission Forward Ok
Transmission Reverse Ok
Automatic Group Select Ok
Service Brake Ok

Park Brake Ok, Little weak

Electrics Ok Retarder Ok

Tires

Axle 1 / RHS mm (%) / LHS mm (%) 80% /80%

Axle 2 Inside / RHS mm (%) / LHS mm (%) 40% / 40%

Axle 2 Outside / RHS mm (%) / LHS mm (%) 40% / 40%

Tire Size 315 (80R22.5)

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

